

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SURVEY &
REMONUMENTATION

MAR 02 2001

For corners in

Ontonagon County

Located in:

Corner Code #

1. Public Land Survey

T48N R39W 1-13
T47N R39W 1-1

2. Property Controlling
in Section
3. Miscellaneous
Property in Sec.

S T R
S T R
S T R
S T R

4. Lot No. , Recorded Plat
5. Private Claims

SECTION

1P

JUDITH D. ROEHM

Ontonagon County

LC 5/357

Page 1 of 1

JEM Date 01/03/2001

Time 14:38:37

9.00

RECORDING FEE:

Register of Deeds Stamp & File Number

I, Joseph C. Domitrovich, in a field survey on September 13, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(1-13) Corner Common to Sections 34 & 35, T48N, R39W and Sections 2 & 3, T47N, R39W.

1847 - Austin Burt set a Hemlock Post with ties:

18" Hemlock N 63°E 27 links
12" Yellow Birch N 32°W 13 links

I found no record of subsequent restoration.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found no remains of original corner or accessories. At the corner position I found a 3/4" iron pipe 3' above ground in an old N-S fallen fence and rock pile. The pipe falls 26' North of a fallen Fence to the West. The position marked by the iron pipe works well with distances to section corner 1 mile west, 1 mile north and 2 miles to the East. I have accepted the position of the iron pipe as the best representation of the true section corner position. I replaced the pipe with a county monument.

Research on file with County Remonumentation Representative.

PEER GROUP APPROVED

Earl W. Applekamp
COUNTY REMONUMENTATION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 12-19-00

Corner is a 3/4" x 48" aluminum rod with a 3" diameter aluminum cap stamped to read: COUNTY REMONUMENTATION; T48N, T47N, R39W; S. 35, S. 34, S. 2, S. 3; P.S. 37273; 2000. Ties:

4" Ironwood N 09°E 5.22' (Existing 1995 Connor Forest Tag)
5" Ironwood S 85°E 17.18'
10" Hard Maple S 03°E 8.47'
4" Soft Maple S 49°W 16.43'
Steel Sign Rail West 1.96' (to face)

NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted. Bearings shown between corners are on assumed basis, for reference only.



Signed by

Joseph C. Domitrovich

Date

12/19/00

Surveyor's Michigan License No. 37273

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995