

**LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970**

MAR 02 2001

SECTION

For corners in

Ontonagon County

Located in:

Corner Code #

1. Public Land Survey

T48N R39W K-13

T47N R39W K-1

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

4. Lot No.

, Recorded Plat

5. Private Claims

JUDITH D. ROEHM

Ontonagon County

1P

Page 1 of 1

LC 5/370

JEN Date 01/03/2001

Time 14:39:38

RECORDING FEE:

9.00

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		6		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Joseph C. Domitrovich, in a field survey on September 13, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(K-13) Corner Common to Sections 35 & 36, T48N, R39W and Sections 1 & 2, T47N, R39W.

1847 - Austin Burt set a Hemlock Post with ties:

12" Sugar

N 45°E

39 links

16" Sugar

N 33°W

13 links

I found no record of subsequent restoration.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found no remains of the original corner or accessories. I re-established the corner position by single proportionate measurement between the SE corner of Section 36 and the SW corner of Section 35. A tree painted up by foresters falls 50' +/- to the East of this position. I have accepted and Monumented the single proportionate position as the best representation of the true section corner.

Research on file with County Remonumentation Representative.

DEED GROUP APPROVED

Earl W. Applikans
COUNTY SUPERVISOR 12-19-00

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 2 1/2" x 30" aluminum pipe stamped to read: COUNTY REMONUMENTATION; T48N, T47N, R39W; S. 35, S. 36, S. 2, S. 1; P.S. 37273; 2000. Corner falls on the extension of a snowmobile trail to the north and 10' west of a woods road to the south. Ties:

7" Hard Maple

S 62°W

16.65'

8" Hard Maple

N 50°W

10.25'

10" Twin Hard Maple

N 42°E

19.18'

7" Hard Maple

S 87°E

50.97'

Steel Sign Rail

South

0.90' (to face)



NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted. Bearings shown between corners are on assumed basis, for reference only.

Signed by

John C. Domitrovich

Date

12/19/00

Surveyor's Michigan License No. 37273