

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

MAR 02 2001

For corners in

SECTION

Ontonagon County

Located in:

Corner Code #

1. Public Land Survey

T48N R39W

L-13

T47N R39W

L-1

T R

T R

T R

T R

T R

T R

2. Property Controlling
in Section

S

T

R

S

T

R

3. Miscellaneous
Property in Sec.

S

T

R

S

T

R

4. Lot No.

, Recorded Plat

5. Private Claims

JUDITH D. ROEHM

Ontonagon County

1P

Page 1 of 1

LC 5/371

JEM Date 01/03/2001

Time 14:40:00

RECORDING FEE:

9.00

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Joseph C. Domitrovich, in a field survey on September 18, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(L-13) 1/4 Corner Common to Sections 36, T48N, R39W and Section 1, T47N, R39W.

1847 - Austin Burt set a Hemlock post with ties:

14" Sugar	N 55°E	36 links
20 Basswood	N 29°W	23 links

I found no record of subsequent restoration.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found no remains of original corner or accessories. Corner falls at an intersection of county roads south and east. At the approximate intersection of centerlines of these roads I found a 1" drillrod. This drillrod falls 21.33' east of being midway between section corners and it falls 14.09' north of a line between them. I did not accept the drillrod. Instead, I monumented the single proportionate (Midway and on-line) position as the best representation of the true corner. This position works well with remains of old fence going west and falls on remains of north-south fence.

Research on file with County Remonumentation Representative.

PEER GROUP APPROVED

Earl W. Applekamp
COUNTY REMONUMENTATION

12-19-00

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 2 1/2" x 30" aluminum pipe with a 3" diameter aluminum cap stamped to read: COUNTY REMONUMENTATION; T48N, T47N, R38W; S. 36, S. 1; 1/4; 2000; P.S. 37273. Corner falls west of county road on a sharp curve. Ties:

22" Hard Maple	N 10°W	19.76'
Steel Sign Rail	North	1.00' (to face)
1" Drillrod	N 56°E	25.58'
Power Pole	S 66°E	63.69'
7" Basswood	S 34°E	3.35'

NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted. Bearings shown between corners are on assumed basis, for reference only.



Signed by

Joseph C. Domitrovich

Date

12/19/00

Surveyor's Michigan License No. 37273