

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ONTONAGON  
(County)

Located In:

Corner Code #

1. Public Land Survey

T48N R 40W

E-1

T49N R 40W

E-13

T R

T R

2. Property Controlling  
In Section

S

T R

S

T R

3. Miscellaneous  
Property in Sec.

S

T R

S

T R

SURVEY &  
REMONUMENTATION

MAR 02 2001

SECTION

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

Section Corner common to Sections 4 & 5, T48N R40W &  
Sections 32 & 33, T49N R40W.  
2000

I, Earl W. Applekamp, in a field survey on Sept. 13, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original Corner established by William A. Burt, U.S. Deputy Surveyor, summer of 1847. Set Sugar Post.

ORIGINAL BEARING TREES:

8" Sugar N45°E 13 Links ( 8.58 Feet)  
20" Hemlock N45°W 26 Links (17.16 Feet)

DEED GROUP APPROVED  
Earl W. Applekamp  
COUNTY SAGINAW  
9-27-00

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. There was a U.S. Forest Service tag, dated August 1969 indicating corner was 2.7 feet S44°E to approximate corner. Champion Inc. recently logged to a line West & South from this location. U.S. Forest Service have dug out potential bearing tree stump holes without obtaining a positive location for the corner. The calculated position is consistent with the approximate location mentioned above. It is also in agreement with GLO call to a creek South and top of hill. I re-established the corner at the position given in 1969 as being the accepted position.

Research on file with the Ontonagon County Remonumentation Program Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2½"X30" split base aluminum pipe with a 3" cap stamped to read: County Remonumentation, T48N, T49N, R40W, S4, S5, S32, S33, 2000, P.S. 17610. I established 3 bearing trees and a reference object.

Nail in 11" Maple S11°W 34.59' - Nail in 10" Maple S58°E 31.16'  
Nail in 9" Maple N28°W 53.64' - 6' Steel Sign Post North 0.65'



Signed by Earl W. Applekamp

Date September 26, 2000

Surveyor's Michigan License No. 17610