

SURVEY & REMONUMENTATION

MAR 02 2001

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

ONTONAGON
(County)

Located In:

Corner Code #

1. Public Land Survey

T48N R 41W

J-1

T49N R 41W

J-13

T R

T R

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

JUDITH D. ROEHM

1P

Ontonagon County

Page 1 of 1

LC 5/343

JEM Date 11/01/2000

Time 12:12:23

RECORDING FEE:

9.00

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

$\frac{1}{4}$ Corner common to Sections 2 & 35, T48N, T49N, R41W.

2000

I, Earl W. Applekamp, in a field survey on Oct. 5, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6	5			4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original Corner established by William A. Burt, U.S. Deputy Surveyor, summer of 1847. Set Hemlock Post.

ORIGINAL BEARING TREES:

36" White Pine N70°E 19 Links (12.54 feet)
16" Cedar N75°W 10 Links (6.60 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. Construction of the Norwich Road and farming on both sides of the road, destroyed all evidence. Corner was re-established on line between opposite Section Corners East and West and in the center-line of the paved Norwich Road.


Research on file with the Ontonagon County Remonumentation Program Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 5/8"x12" Rebar with a 3" Stamped cap 1" below top of blacktop. I established a reference monument, a 2 1/2"x30" split base aluminum pipe with a 3" cap stamped to read: County Remonumentation, T48N, T49N, R41W, S2, S35, $\frac{1}{4}$, R.M., 2000, P.S. 17610. I established three bearing objects.

Nail in P. Pole S16°W 104.66' - REF. MON. East 34.34'
Nail in P. Pole N07°E 197.49' - 6' Steel Sign Post East, 35.04'

DEED GROUP APPROVED
Earl W. Applekamp
COUNTY REGISTER



Signed by Earl W. Applekamp
Surveyor's Michigan License No. 17610

Date October 7, 2000