

MAR 02 2001

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

Ontonagon County	Located in:	Corner Code #
1. Public Land Survey	T51N R38W	F-7
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

JUDITH D. ROEHM
Ontonagon County
Page 1 of 1
JEM Date 01/03/2001 Time 14:37:21
RECORDING FEE: 9.00
LC 5/364

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							

I, Joseph C. Domitrovich, in a field survey on December 5, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F-7)- 1/4 Corner Common to Sections 16 and 21, T51N, R38W

1846- H. and S.W. Higgins set a 1/4 post
12" Sugar S 70°E 7 links
12" Balsam N 60°W 6 links

I found no record of subsequent restoration.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found no remains of the original corner or accessories. The area around the corner has been repeatedly logged since the time of the original survey. I have treated this corner as lost and have reestablished it by single proportionate measurement. Corner falls 5' south of a painted and blazed East-West line.

Research on file with County Remonumentation Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 3/4" x 48" aluminum rod with a 3" diameter aluminum cap stamped to read: COUNTY REMONUMENTATION; T51N, R38W; 1/4; S. 16, S. 21; 2000; P.S. 37273.

Ties:

5" Hard Maple	S 80°W	3.90'
6" Hard Maple	N 16°W	8.84'
8" Hard Maple	N 60°E	11.20'
Steel Sign Rail	South	0.42' (to face)
NW Cor. Sec. 21	N 88°01'01"W	2615.51'
NE Cor. Sec. 21	S 88°01'01"E	2615.51'

NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted. Bearings shown between corners are on assumed basis, for reference only.



PEER GROUP APPROVED
Earl W. Applkamp 12-19-00
COUNTY REMONUMENTATION

Signed by *J. C. Domitrovich*

Date 12/19/00

Surveyor's Michigan License No. 37273