

MAR 02 2001

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Ontonagon County

Located in:

Corner Code #

1. Public Land Survey

T51N R38W H-7

2. Property Controlling
in Section

S T R
S T R

3. Miscellaneous
Property in Sec.

S T R
S T R

4. Lot No. , Recorded Plat

5. Private Claims

JUDITH D. ROEHM

Ontonagon County

1P

Page 1 of 1

LC 5/354

JEM Date 12/08/2000

Time 11:42:34

RECORDING FEE:

9.00

Register of Deeds Stamp & File Number

I, Joseph C. Domitrovich, in a field survey on November 8, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(H-7) ¼ Corner Common to Sections 15 & 22; T51N, R38W.

1846 - H. & S.W. Higgins set a post with ties:

10" Sugar	S 50°E	11 links
8" Sugar	N 70°W	8 links

1997 - Mead Paper Corner records indicate that they set a 4 x 4 wood post at the intersection of lines.

7" H. Maple	S 88°W	10'
9" H. Maple	N 82°E	16.5'
11" Basswood	S 28°E	12.5'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found no remains of the original corner or accessories. I found the 4 x 4 post called for by Mead. I found remains of a very old fence running North and East. I re-established the corner position at the intersection of these two fences. This position works well with the 4 x 4 post set by Mead and is the position of the ¼ corner accepted and used for many years. Distances to Section Corners east and west differ from record GLO but this is not inconsistent with work done elsewhere in this township by the original surveyors. I have accepted the fence intersection as the best representation of the original ¼ corner position.

Research on file with County Remonumentation Representative.

DEED GROUP APPROVED

11-29-00 Earl W Applebury

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 2 ½" x 30" aluminum pipe with a 3" diameter aluminum cap stamped to read: COUNTY REMONUMENTATION; T51N, R38W; S. 15, S. 22; ¼ 2000; P.S. 37273. Ties:

10" Ash	N 29°W	11.67' (Existing Blaze)
6" Hard Maple	S 82°E	10.07' (Existing Blaze)
6" Hard Maple	S 24°E	21.20'
Steel Sign Rail	West	0.67' (to face)
NE Cor. Sec. 22	N 89°35'56"E	2576.97'
NW Cor. Sec. 22	S 88°26'42"W	2711.98'

NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted. Bearings shown between corners are on assumed basis, for reference only.

Signed by Joseph C. Domitrovich

Date 11/28/00

Surveyor's Michigan License No. 37273

