

# LAND CORNER RECORDATION CERTIFICATE

## Filing Requirement of Act 74, Mich. P.A. 1970

Ontonagon County

 of 2  
 LC 5/288  
 Date 05/12/2000 Time 16:31:02  
 RECORDING FEE: 11.00

For corners in

Ontonagon County	Located in:	Corner Code #
1. Public Land Survey	T52N R39W	K - 13
	T R	
	T R	
	T R	
2. Property Controlling	S T R	
in Section	S T R	
3. Miscellaneous	S T R	
Property in Sec.	S T R	
4. Lot No.	Recorded Plat	
5. Private Claims		

### SURVEY & REMONUMENTATION

MAR 02 2001

### SECTION

Register of Deeds Stamp &amp; File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Joseph C. Domitrovich, in a field survey on May 22, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

#### A. Description of original monument and accessories and/or subsequent restoration:

(K - 13) Standard Corner Common to Sections 35 & 36, T52N, R39W.

1845 - William A. Burt set a Fir Post with ties:

18" Sugar	N 16°E	26 links
18" Hemlock	N 13°W	28 links

1845 - Austin Burt, in T51N R39W subdivision, intersected 12 links (7.92') East of this corner and set a closing corner.

I found no record of subsequent restoration.

#### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found no remains of the original corner or accessories. North - South Calumet Road now runs over corner position. Corner position now falls at the Northerly edge of a power line clearing, 50' North of the centerline of the power line. I found a 1" iron pipe defining the Easterly R.O.W. and the township line. After extensive retracement along the township line I have determined that the closing corner falls on centerline of Calumet Road (33' West of the R.O.W. pipe). I therefore established the standard corner the GLO distance, 7.92', West of the closing corner. This position works well with other standard corners to the West, as well as with Section corners to the North.

Research on file with County Remonumentation Representative.

#### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 5/8" x 12" iron pin with a 3" diameter aluminum cap stamped to read: COUNTY REMONUMENTATION; T52N, R39W; S.C.; S. 35, S. 36; 2000; P.S. 37273. I also established a Reference Monument (R.M.) to the West, a 2 1/2" x 30" aluminum pipe with a 3" diameter aluminum cap stamped to indicate that the standard corner is N 89°51'E, 21.43'. Ties to the Corner:

10" Soft Maple	N 37°E	55.26'
1" R.W. Pipe	S 89°57'43"E	40.92'
Closing Corner		
Sec. 1&2 T51N R39W	S 89°57'43"E	7.92'
8" Basswood	S 52°E	46.99'
Power Pole	S 13°W	140.44'
R.M.	S 89°51'06"W	21.43'
S 1/4 Cor. Sec. 35	S 89°52'46"W	2638.19'
NE Cor. Sec. 35	N 00°11'57"W	5279.00'

SEE SKETCH ON BACK

NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted.

Signed by Joseph C. Domitrovich

Date 5/24/00

Surveyor's Michigan License No. 37273

