


FEB 2 5 1994

COMMISSION LAND CORNER RECORDATION CERTIFICATE

Fo	ئىلىنىڭ Or corners in	Filing Require	ement of Act 74, Mich. P.A.	1970
,	Osceola	Located In:	Corner Code ≠≠	•
	(County)			
1.	Public Land Survey	т <u>19N</u> в <u>——</u>	A-10	APPROVED LAND CORNER
		T R		P.A. 345 OF 1990 Osceola County
		T B		mother W. A.
2.	Property Controlling	T R S T R		8 Dec. 1993
	in Section	S T R		
3.	Miscellaneous	S R		Register of Deeds Stamp & File Number
	Property in Sec.	S T R		
4.	Lot No	Recorded Plat	•	
5.	Private Claims			A B C D E F G H I J K L
				2 6 5 4 3 2 - 1
				3
ı	Matthew McClu	ing De	ecember 4, 199	3 4 7 1 1 1 1 1 2
do	nereby certify that under re	quirements of P.A. 74, Michigan P.A. o	of 1970, the corner points mentioned	
in cu	lines 1 and 2 above were i	in conformance with regulations and ructions of the United States Departr	rules therefore as required in the	e ['''
Ma	inagement or by a decree of	a Court of Law and/or that the corner	points mentioned in lines 3, 4 and 5	
ab Co	ove were in conformance w ourt of Law: established.	ith the rules of the Michigan Board of re-established, monumented, re-m	Land Surveyors or by a Decree of a	
	pressed below:	ve versioned, mendinende, re m	onamented, recovered, round as	10 30 29 28 27 26 25
NC		corners, all in the same town and	d range, may be recorded	11)
	on this certificate	-		12 31 32 33 34 35 36 13 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
В.	Beech 7" Beech 7" From 1891 to program, in w most part, a at each gover tile per corr Description of corner of Found 1/2 Roof Monument over	od post 40.00 chains S52W 23 lks. N65W 17 lks 1904 approximately which surveyors Temp 3" glazed tile fill frament set corner in the placed atop of evidence found and/or method and and tile 3" below	s from the South. Osceola County hole and Trumbull, led with cinders for the township. The each other, (complied in restoring or reestablished surface. Platile and drove to	hing comer:
J.	Description of monume	nt for corner and accessories es	tablished to perpetuate locatin	g the position of the corner:
	Corner M-10. 1" pipe 18" i Power po Telephon Pipe gat	Osceola County Monu	ment, which is a second of the control of the contr	3" brass cap mounted on a Witt.
			,	THE THE PARTY OF T
				OF MICK
				ANG AMATTHEW
	a. 0	12000	Ť	December ZA. MOSJUNG
igr	ned by Mather	M'Cling	Date	LAND
ur	veyor's Michigan License	e No		SURVEYOR OF SURVEYOR
		# <u>*</u> 1		APPROVED BY MICHEMAN STATE BOARD OF LAND SURVEYORS JAN 28, 1971 PEVISED MAN 14, 1975
		L1De	er A Page 118	1303/ ROYSERVAN, 1983



93 DEC 10 PH 2:51

Many Crayford

thereby making the corner 4 feet long. Sometimes a solid tile, with a cross in the top was used, and sometimes a 1/2" iron bars were added to the tile. Notes of the work were kept in ledgers, and given to the townships, and 5 of the townships have been recorded in the County records.

This corner is recorded in the Rose Lake Twp. Book, pages 12 & 13, with no description of corner material.

PA. 132 certificate dated 16 Mar. 1988, by McClung.