SURVEY & REMONUMENTATION

SEP 1 5 1994

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Oscorla Comer Code=## Comer Code=## APPROVED LAND CORNER P.A. 3.5 of 1990 Oscosy County	COMMISS	SION Filing Require	ement of Act 74, Mich. P.A	l. 1970	
1. Problet Land Survey T 18N R TM T R T R T R T R T R T R T R		Located In:	Corner Code ##	P.A. 345 OF 1990	
2. Property Controlling S T R S IS R S IS R R R Register of Deeds Stamp & File Number Property in Section S T R R Recorded Plat R R R R R R R R R R R R R R R R R R R	1. Public Land Survey	T R T R		Marthey Mile	
1. Matthew McClums lists survey on 23 July 18 1994 deherely certify mail under requirements of PA 74, Minhigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in contormance with englistions and rules therefore as required in the current mass of survey instructions of the whited States Department of the lines of States of Land Management or by a decree of a Court of Lewand/orthat the corner points mentioned in lines 1, a was a control and a survey and the land of the lines of States of Land Management or by a decree of a Court of Lewand/orthat the corner points mentioned the lines of Land Court of Lewand/orthat the corner points mentioned the lines of Land Court of Law, established, re-established, monumented, recovered, found as expressed below. NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A Description of original monument and accessories and/or subsequent restoration: The resurvey corner was set by deputy surveyor Francis Coleman on July 21, 1856. Set wood post 40,05 chains from the South. (Reestablished Cor) Beech 14" STIE 12 Lks. From 1891 to 1904 approximately, Oscocla County had a remonumentation program, in which surveyors Temple and Trumbull, did the work. For the most part, a 3" glazed tile filled with cinders from a forge, were placed at each government set corner in the township. There were supposed to be 3 tile per corner, placed atop of each other, (continued on back) B. Description of comer evidence found and/or method applied in restoring or reestablishing comer: Found Oscocla County Monument 9" below road surface. Removed same and found 1 1/2" pipe at 18". Excavated to 36" along pipe and found pile of stones around pipe. Removed six stones to depth of 40", and pipe was still soll to represent the corner of school house addition S45W 107.1 feet. Telephone (stub) pole N45W 43.4 feet. 6" W. Pine S40R 73.4 feet. Signed by Matthew Matthew Matthew 13037	in Section 3. Miscellaneous	S T R S T R S T R		Register of Deeds Stamp & File Nun	nber
Matthew McClunga field survey on23 _July				— A B C D E F G H I J	KLM
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: The resurvey corner was set by deputy surveyor Francis Coleman on July 21, 1856. Set wood post 40.05 chains from the South. (Reestablished Cor) Eeech 14" S71E 12 Lks. Eeech 14" S75E 12 Lks. From 1891 to 1904 approximately, Osceola County had a remonumentation program, in which surveyors Temple and Trumbull, did the work. For the most part, a 3" glazed tile filled with cinders from a forge, were placed at each government set corner in the township. There were supposed to be 3 tile per corner, placed atop of each other, (continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found Osceola County Monument 9" below road surface. Removed same and found 1 1/2" plpe at 18". Excavated to 36" along pipe and found pile of atones around pipe. Removed six stones to depth of 40", and pipe was still solid. Reset Osceola County Monument over pipe 8" below road surface. Corner I-9. is Osceola County Monument over pipe 8" below road surface. NE corner of school house addition S45W 107.1 feet. Telephone (stub) pole N45W 44.02 feet. Telephone Pedestal S55W 49.48 feet. 6" W. Pine S40E 73.4 feet. Signed by Mathew Mathew Mathew 13037	I,Matthew_McCludo hereby certify that under red in lines 1 and 2 above were in current manual of survey instruManagement or by a decree of above were in conformance with	Urliga field survey on23 quirements of P.A. 74, Michigan P.A. n conformance with regulations an uctions of the United States Depart a Court of Law and/or that the corne th the rules of the Michigan Board o	3 July 19 of 1970, the corner points mention drules therefore as required in ment of the Interior, Bureau of Lr points mentioned in lines 3, 4 and Land Surveyors or by a Decree	1994 5 ned the and 7 nd 5 8 19 20 21 22 2	1 12 12 13 13 13 13 13 13 13 13 13 13 13 13 13
on this certificate. A. Description of original monument and accessories and/or subsequent restoration: The resurvey corner was set by deputy surveyor Francis Coleman on July 21, 1856. Set wood poet 40.05 chains from the South. (Reestablished Cor) Beech 14" S71E 12 Lks. Beech 14" S75E 19 1ks. From 1891 to 1904 approximately, Osceola County had a remonumentation program, in which surveyors Temple and Trumbull, did the work. For the most part, a 3" glazed tile filled with cinders from a forge, were placed at each government set corner in the township. There were supposed to be 3 tile per corner, placed atop of each other, (continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found Osceola County Monument 9" below road surface. Removed same and found 1 1/2" pipe at 18". Excavated to 36" along pipe and found pile of stones around pipe. Removed six stones to depth of 40", and pipe was still solid. Reset Osceola County Monument over pipe 8" below road surface. Corner I-9. is Osceola County Monument over pipe 8" below road surface. MAITHEM No. 13037 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner of school house addition S45W 107.1 feet. Telephone (stub) pole N45W 44.02 feet. Telephone Pedestal S55W 49.48 feet. 6" W. Pine S40E 73.4 feet. Signed by Matthew M. A. McClun July 23, 1994	expressed below:			10 - 30 29 - 28 - 27 2	625-
A Description of original monument and accessories and/or subsequent restoration: The resurvey corner was set by deputy surveyor Francis Coleman on July 21, 1856. Set wood post 40.05 chains from the South. (Reestablished Cor) Beech 14" S71E 12 Lks. Beech 14" S55W 9 lks. From 1891 to 1904 approximately, Osceola County had a remonumentation program, in which surveyors Temple and Trumbull, did the work. For the most part, a 3" glazed tile filled with cinders from a forge, were placed at each government set corner in the township. There were supposed to be 3 tile per corner evidence found and/or method applied in restoring or reestablishing corner: Found Osceola County Monument 9" below road surface. Removed same and found 1 1/2" pipe at 18". Excavated to 36" along pipe and found pile of stones around pipe. Removed six stones to depth of 40", and pipe was still solid. Reset Osceola County Monument over pipe 6" below road surface. Corner I-9. is Osceola County Monument over pipe 6" below road surface. MAITHEW A. McCLUN LAND SURVEYOR A. McCLUN LAND SURVEYOR SURVEYOR SURVEYOR A. McCLUN LAND SURVEYOR SUR			nd range, may be recorded		5 36
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Corner I-9. is Osceola County Monument, which is a 3" brass cap mounted or a 1" pipe 18" in length. NE corner of school house addition S45W 107.1 feet. Telephone (stub) pole N45W 44.02 feet. Telephone Pedestal S55W 49.48 feet. 6" W. Pine S40E 73.4 feet. Signed by Matthew McMany Date	21, 1856. Set Beech 14 Beech 14 From 1891 to program, in most part, a at each governile per correctile per correctile per correctile found 0 second found 1 1/2" stones around	t wood post 40.05 of S71E 12 Lks. " S65W 9 lks. 1904 approximately which surveyors Tender 3" glazed tile filler filler filler filler filler filler for the set corner is set corner in the set corner is set at a county Monument set county Monument set filler fi	chains from the Sort, Osceola County aple and Trumbull lled with cinders in the township. If each other, (capplied in restoring or reesta 9" below road survated to 36" alon stones to depth	had a remonumentation, did the work. For the from a forge, were place. There were supposed to bontinued on back) blishing corner: face. Removed same and g pipe and found pile of of 40", and pipe was storm of the below road surface.	ed be 3 111 M/CA/GA
NE corner of school house addition S45W 107.1 feet. Telephone (stub) pole N45W 44.02 feet. Telephone Pedestal S55W 49.48 feet. 6" W. Pine S40E 73.4 feet. Signed by Matthew Mc Lang Date	Corner I-9.	is Osceola County	established to perpetuate loc Monument, which i	cating the position of the corner LA	O. 37 SUR
Signed by Matthew M. Clerry Date Date	NE corn Telepho Telepho	er of school house ne (stub) pole N45 ne Pedestal S55W 4	W 44.02 feet. 9.48 feet.	7.1 feet.	
13037	Marth	ow Mc Pleum	Nate	July 23, 1994	
STUTVEYOR STRATE BOARD OF LAND SURVEYORS, JAN.	Signed by Application Surveyor's Michigan Licens	se No130		FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYOR:	IS, JAN. 28, 197

LIBER A PAGE 165

thereby making the corner 4 feet long. Sometimes a solid tile, with a cross in the top was used, and sometimes a 1/2" iron bars were added to the tile. Notes of the work were kept in ledgers, and given to the townships, and 5 of the townships have been recorded in the County records.

I have shown 4 PA. 132 certificates using this corner.

REGISTER OF DEED.