FEB 2 4 2000

& YEVELL

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, Mich. P.A. 1970

SECTION

	corners in	Loc	cated in:	Corner Codes	#				~~		D	mais
1.	Public Land Survey		T 20N	R 8W	J-1				95 25			
			<u>T</u>	R					John Committee of the C	. '		THA PA
			<u>T</u>	R					2	; 	3 2	닦는
			T	R					OF		PH 12:	E S
2.	· · · · · · · · · · · · · · · · · · ·	S	T	R					{		9	EDS
	in Section -	S	<u>T</u>	R		Registe	e of F)eeds	Stan	nn & F	Tie Ni	ımher
3.	Miscellaneous	S	T	R	<u> </u>					.p		
4.	Property in Sec. Lot No Reco	s rded Plat	<u>T</u>	R		Δ	. вс	DE	t F G	. H 1	IJĸ	L M
5.						1				[·•··	
i, Robert L. Wetherell, in a field survey on September 30 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United							6 7 18	5 8 17	9	3 10 15	11 14	1 12 13
States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree							19	20	21	22	23	24
Of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:							30	29	28	27	26	25
	are was reason as explose	ou Monyili				11 12 13	31	32	33	34	35	36
NO	TE: ONLY ONE CORNE	R MAV RI	RECORDE	ED ON THIS CEI	RTIRICATE						. —	

N 1/4 Corner of Section 2, T20N,R8W

A. Description of original monument and accessories and/or subsequent restoration:

1891- L. June
"Set by Measurement" Set 3 Clay Tile

1923-1956 F. McClung Highland Twp Book Pages 84 & 85 #3- Maple NE 27.1' #4- Maple SW 27.7" Dist. West 2649.50 Dist East 2660.10'

1998-M. McClung 13037

Fd. Iron & Cap 13037 and Iron 42" below surface

Set Osceola County Monument #5- P. Pole (Center) N18W 76.45° #6-6" Elm \$12E 25.83

#7-12" Butternut S65W 59.48" #8-Top Center Tele. Ped. \$82W 128.80'

Dist. East 2658.87 Dist. West 2648.88'

B. Description of corner evidence found and/or method applied in restoring of reestablishing corner:

Found Osceola County Monument +/- 1' South of the C/L of East and West Road and in line with fence South.

Condition of the accessories are as follow: #3 Gone, #4 Gone, #5 Found in good condition, #6 Found in good condition, #7 Found in good condition and #8 Found in good condition.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I accept the Osceola County Monument (1 1/2" pipe with an Osceola County Remon Cap) as a substantial marker of the corner OI WISHING and is accepted as a careful and faithful reestablishment of the position of the original corner.

P. Pole N18W 76.450'(Center) - #5 6" Elm S12E 25.9'(Nail on W. side) - #6 12" Butternut S65W 59.15'(Nail on SE side) - #7 Top Center Tele. Ped. S82W 128.80' - #8

ount I. Wetherell

Surveyor's Michigan License No. 24624

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS

10

REVISED MAY 14, 1975

ADAPTED FOR WORD PROCESSING JAMUARY, 1999

ROBERTI

WETHERELL

LAND SURVEYOR 24624

CAND

APPROVED LAND CORNER P.A. 345 OF 1990 Osceola County

10-21-99 W

Liber B Page 546