

DEC 16 1996

COMMISSION

JUDITH D. ROEHM
Ontonagon County
LC 4/ 47 JEM Fee: 9.00
Page 1 of 1

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>ONTONAGON</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T 48NR 40W	G-9
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Section Corner common to Sections 21, 22, 27 & 28, R48N R40W.

I, Earl W. Applekamp, in a field survey on April 24, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by J. Wells Burt, U.S. Deputy Surveyor in May 1851. Set Wood Post.

ORIGINAL BEARING TREES:

W. Birch	10"	N25°W	3 links
Fir	8"	N58°E	19 links

PEER GROUP APPROVED

Earl W. Applekamp 5-07-96
COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

At the apparent corner location I found a 2" pipe 14" below top of blacktop road. Location is consistent with original survey natural feature calls. Two roads intersect at this location. The location of the 2" pipe was accepted as the correct position for the corner.

Research on file with the County Remonumentation Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 3/4"x15" aluminum rod (above the 2" pipe) with a 3 1/4" cap 1 1/2" below top of blacktop, stamped to read: County Remonumentation, S21, S22, S27, S28, T48N R40W, 1996, P.S. 17610. I established one reference monument, a 2 1/2"x30" aluminum pipe with stamped cap and three other reference objects.

REF. MON.	N46°-03'-26"E	54.48'	Fence post	S67°-16'-36"W	85.98'
21" Oak	S38°-12'-10"E	107.93'	7" Aspen	N24°-09'-30"E	79.92'



Signed by Earl W. Applekamp
Surveyor's Michigan License No. 17610

Date April 27, 1996