

LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ONTONAGON (County)	Located In:	Corner Code #
1. Public Land Survey	T 48NR 41W	E-8
	T ___ R ___	_____
	T ___ R ___	_____
	T ___ R ___	_____
2. Property Controlling in Section	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____

SURVEY &
 REMONUMENTATION

APR 07 1998

SECTION

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

1/4 Corner common to Sections 20 & 21, T48N R41W.

I, Earl W. Applekamp, in a field survey on Sept. 22, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Wells Burt, U.S. Deputy Surveyor, June 14, 1851. Set Wood Post.

ORIGINAL BEARING TREES:

12" Maple S74°W 10.56 feet
 10" Spruce N30°W 19.80 feet

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. Corner position is in area which has been logged several times. No farming was performed in this area. I found remnants of a fence line running West, about 100 feet West of where I established the corner. There are no original feature calls in the area of the corner. I re-established the corner by single proportionate measure between opposite section corners North & South.

Research on file with the Ontonagon County Remonumentation Program Representative.

BEER GROUP APPROVED
Earl W. Applekamp
 COUNTY REPRESENTATIVE 10-08-97

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2 1/2" x 30" split base aluminum pipe with a 3" cap stamped to read: County Remonumentation, T48N R41W, 1/4, S20, S21, 1997, P.S. 17610. I established three bearing trees and bearing object.

5" Elm S10°W 7.06' - 5" Elm Due East 24.50'
 4" Elm N86°W 48.89' - Steel Sign Post, North 1.28'



Signed by Earl W. Applekamp
 Surveyor's Michigan License No. 17610

Date September 22, 1997