

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Ontonagon (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 33 T 51N R 37W	F12
	S 32 T 51N R 37W	9
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 9 04/14/2010 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F12) Center of Section 33. Not established in the original survey. Corner is shown has having been
established on a mining company survey ca. 1907-1910 of the subdivision of Sections 31, 32, and 33.
Dimensions from Quarter corner E12 and 1/16 corner #5, Sec. 33 are given as S88 deg. 22'30"E, 2767.4'
and S1 deg. 50'30"W, 1318.0', respectively. No monument type noted. The survey drawing, or a copy
of it, resides at the offices of Steven Hein PS, Laurium, MI.

(9-Sec. 32) East 1/16 corner, Section 32. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F12) No monumentation was found at the corner position. Reestablished the mining company position
using found monumentation on Section 33 and the bearing and distance measurements given on the
drawing. Specifically, the corner was reestablished S88 deg. 22' 16"E, 2766.95' from Quarter corner
E12, and S1 deg. 47'03"W, 1319.19' from 1/16 corner #5, Sec. 33 (True bearings). This position was
chosen as it seems to fit best with the various mining company measurements which concern the
location of this corner.

(9-Sec. 32) Established the corner midway and on a straight line between Center of Section 1255.11'
west and Quarter corner 1255.11' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F12) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
6" Sugar N52W 13.2' mrkd "C1/4 BT"
5" Y.Birch N55E 28.7' do
5" Y.Birch S35E 4.7' do
19" Cedar S01E 27.5' do
Set Cedar post adjacent. Bearings are magnetic.

(9) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
10" Hemlock S56E 2.5' mrkd "1/16S BT"
16" Sugar S10E 4.4' do
16" Hemlock S84W 19.1' do
11" Sugar N38W 13.3' do
Set Cedar post adjacent. Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 09/07/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division

