LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 <u>1</u>P Ontonagon County Remonumentation Comier D. ROEHM Ontensson County For comers in 62 Page 1 of 1 LÜ Time 10:45 JDR Rec. Date 05/26/98 Located in: Comer Code # **Ontonagon County** RECORDING FEE: 9.00 T51N R41W 1. Public Land Survey T R T R R Т Ţ R 2. Property Controlling SURVEY & S T in Section REMONUMENTATION R T 3. Miscellaneous S S R Property in Sec. JAN 1 1 1999 Register of Deeds Stamp & File Number 4. Lot No. . Recorded Plat 5. Private Claims SECTION 2 3 4 I, Joseph C. Domitrovich, in a field survey on March 31, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of 5 6 survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above 8 were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: 10

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded

(K-4) - 1/2 Corner common to Sections 11 and 12, T51N, R41W

1846 - S.W. Higgins set a post:

on this certificate.

10" Sugar

S60°E 15 links

12" Hemlock

N40°W 27 links

1962 - Michigan State Highway Dept. (M.S.H.D.) Highway construction plans for M-64 show the corner as a 4" squared cedar post with a Forest Service tag and established 3 witnesses to it:

8" Maple 4" Maple East 2.80"

South 7.32'

4" Maple

S40°W 13.90'

They also show a 1/16 corner established from this post, on line with Meander Corner (Witness Corner to Section Corner which now falls in Lake Superior) to the North and 1320.31' distant. This corner is referenced to highway centerline control.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found no remains of the Original Corner or accessories. Corner now falls in a heavily clearcut area and appears to have been farmed in the past. I also could find no remains of the M.S.H.D. corner or witnesses. I did, however, recover corners and Highway control to which the corner was referenced.

I recreated the M.S.H.D comer position from Highway centerline control. This position works well with distances to 1/16 corner and Meander corner to North. It falls 6 feet east of a fallen fence to the North and 26' east of a jog in a newer fence to the south. It falls 1' south of a fallen East-West fenceline and 40.12 feet east of a 1" pipe. The M.S.H.D position has been used to establish the 1/16 corner to the North which has been used in numerous surveys of small parcels of land in the Government Lots in Section 11. It also best matches the the fencelines and occupation. I have accepted this position as the 1/2 comer and have monumented it as such.

Research on file with County Remonumentation Representative.

C. Description of monument for comer and accessories established to perpetuate locating the position of the comer: Corner is a 5/8" x 24" rebar with a 3" diameter aluminum cap stamped to read: COUNTY REMONUMENTATION; T51N, R41W; 1/4; S.11, S.12; 1998; P.S. 37273.

%" fron Pin

Witnesses: 24.23 N22°W 4" White Birch 33.06 N42°F 7" Soft Maple 28.94 4* Poplar S84°E 1" Iron Pipe West 40.12

0.89'(to face)

LU -13-98

Steel Sign Post South S00°54'29"W SW cor. Sec. 12

N01°20'07"E

2786.20

1320.33' (North 1/16 corner common to sections 11 and 12)

NOTE: Bearings are magnetic. Distances are to a nail in side of the witness object unless noted.

Domit h Signed by

Date

Surveyor's Michigan License No. 37273

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISEO MAY 14, 1975 REVISED JAN., 1983 REVISED COT., 1995

DE MICHIG

JOSEPH

DOMITROVICH

LAND SURVEYOR

No. 27272

CAND S

151N R41W K4 doc