

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ONTONAGON
(County)

Located in:

Corner Code #

1. Public Land Survey

T51N R42W

K-6

T___ R___

T___ R___

T___ R___

2. Property Controlling
in Section

S___ T___ R___

S___ T___ R___

3. Miscellaneous
Property in Sec.

S___ T___ R___

S___ T___ R___

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

$\frac{1}{4}$ Corner common to Sections 13 & 14, T51N R42W.

I, Earl W. Applekamp, in a field survey on June 08, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by S.W. Higgins, U.S. Deputy Surveyor in the summer of 1846. Set Wood Post.

ORIGINAL BEARING TREES:

12" Hemlock	S20°W	5.28 feet
14" Cedar	N63°E	7.92 feet

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. I did find a yellow tag and a 1 3/4" pipe about 14 feet West of the calculated position. The tag was dated 1970 but had the wrong township on it. There was no evidence of the bearing tree remains at the pipe. No evidence was found as to who or how this pipe was set. Because of this I set the corner by single proportionate measure and on line between opposite Section Corners North & South.

Research on file with the Ontonagon County Remonumentation Program Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2 1/2"x30" split base aluminum pipe with a 3" cap stamped to read: County Remonumentation, T51N R42W, S13, S14, $\frac{1}{4}$, 1998, P.S. 17610. I established 3 bearing trees and a reference object.

Nail in 6" Maple	S08°W	9.53'	-	Nail in 6" Maple	N40°E	24.01'
Nail in 9" Maple	N57°W	28.34'	-	6' Steel Sign Post	East	1.04'

PEER GROUP APPROVAL

Earl W. Applekamp 6-17-98
COUNTY REMONUMENTATION

Signed by Earl W. Applekamp
Surveyor's Michigan License No. 17610

Date June 12, 1998