

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Ontonagon (County) Located In: Corner Code #
1. Public Land Survey T 52N R 37W E13 (GCDB 300100)
2. Property Controlling in Section S 33 T 52N R 37W 2 (GCDB 360200)
3. Miscellaneous Property in Sec.
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 12 columns (A-M) containing numbers 1-36 and a grid for recording deed stamps.

I, Stephan J. Szyszkoski, in a field survey on 2 09/10/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(E13) Section corner common to Sections 32-33 T52N-R37W and Sections 4-5 T51N-R37W. 1845 - Established by W.A.Burt, Deputy Surveyor. Set post. Sugar 12" N66°E 43 links; Sugar 14" N19°W 46 links. 1846 - S.W.Higgins, Deputy Surveyor, marked two additional bearing trees: Sugar 8" S60°E 6 links; Hemlock 24" S37°W 50 links. 1992 - K.L.Sackett, RLS found and accepted a 1"ID iron pipe and used it to reestablish 1/4 corners E12 and F13, T52N-R37W. An LCRC was, apparently, not placed in the record in 1992.

(2-Sec. 33) East 1/16 corner between Sections 28 and 33. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E13) The original post and accessories were not recovered. Found a 1"ID iron pipe, projecting about 2.6 ft. a.g., its position conforming well with the K.L.Sackett record with respect to E11 and E12, as well as with F13 and G13. Accepted same as marking the 1992 position and the best available evidence of the position of the original corner.

(2-Sec. 33) Established the position for the corner midway and on the Section line between Quarter corner 1324.15' west and Section corner 1324.15' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E13) Found 1" ID I.pipe, 31" a.g., placed 4" alum. MDNR cap in the top of it. Set measuring nail with MDNR tag in the side of: 11" Sugar N86°W 32.45' mrkd "S32 NBT" 25" Sugar N05°W 13.4' do 13" Sugar N50°E 6.65' do Power Pole S10°W 42.85' E= 7846201.909 N= 231850.218

(2) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 16" Sugar N03°E 12.65' mrkd "1/16S BT" 4" Y.Birch N46°E 5.20' do 4" Sugar S64°E 15.45' do 11" Sugar S69°W 6.45' do Set sq'd cedar post adjacent. E= 7847427.590 N= 233446.993

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum. Coord. Ref.=NGS PID RL0503: N= 233736.672 m. E= 7856830.965 m.

Signed by [Signature] Surveyor's Michigan License No. 33986

Date 09/23/2015

For the Michigan Department of Natural Resources, Forest Resources Division

