

SURVEY & REMONUMENTATION

DEC 16 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

TIMOTHY D. EDEHM
Ontonagon County
LC 4-133 JEM Feet: 9.00
07/12/96 15:06
Page 1 of 1

For corners in
Ontonagon Located In: Corner Code #
(County)

1. Public Land Survey T 52N R 40W
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Section S T R

1-11/12

001

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Joseph C. Domitrovich, in a field survey on June 18, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2			
3												
4	7		8		9		10		11		12	
5												
6	10		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

(1-11/12) Meander Corner Sections 34 & 35, T52N, R40W

1845 - William A. Burt set Meander post 1294.26' north of 1/4 post.
10" White Pine N 85° E 20 links

1945 - Highway M-64 R.O.W. drawings show corner 1085.10' north of 1/4 corner, but do not indicated what corner is.

1965 - M.S.H.D. M-64 Highway construction plans show corner 1061.36' north of 1/4 corner and give angle and distance to it off of highway centerline-control. They call for corner as being a 1/2" iron pin and give 3 witnesses to it.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original corner and accessories have been washed out by drastic shoreline erosion. Both highway department corner positions have also been destroyed by erosion. I recreated the highway department's 1965 position using centerline control and placed a witness corner to the Meander corner on that line and on high ground. This position works well with other corners and with gravel road running to south. I accepted this position as the witness corner to the meander corner and have monumented it as such.

Research on file with County Remonumentation Representative.

PEER GROUP APPROVED

Paul W. Applekamp
COUNTY REPRESENTATIVE

07-08-96

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 2" x 30" aluminum pipe with a 3" diameter aluminum cap stamped to read: W.C.M.C. S.34, S.35; T.52N., R.39.W.; 1996; P.S. 37273. Corner falls at the edge of a lawn and on the extension of a gravel road to south. No steel sign post was placed here because of corner location.

Witnesses:

NW Corner of Foundation	N 74° E	90.12'
6" Cedar	S 45° E	78.41'
10" Soft Maple in Clump	S 57° W	47.38'
14" White Pine	S 75° W	51.74'
8" Soft Maple in Clump	N 69° W	26.55'

NOTE: Bearings are magnetic. Distances are to nail in side of witness objects unless noted.

Signed by J. C. Domitrovich

Date 7/3/96

Surveyor's Michigan License No. 37273

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

