

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Presque Isle

(County)

Located In

Corner Code #

1. Public Land Survey

T

33N

R

2E

I-10

T

2. Property

Controlling in
Section

S

T

R

S 27

T

33N

R

2E

14

3. Miscellaneous

Property in Section

S

T

R

S

T

R

4. Lot No:

Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on June 18, 2007 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

I-10 G.L.O. G.H. Cannon, 1851, Set quarter section post

Wit: Spruce Pine 8" N63°W 25 links

Spruce Pine 8" S70°E 2 links

14- Michigan Department of Conservation surveyor Marcus Schaaf R.L.S. #3104 sunk iron for corner while surveying in the area circa 1940. No witnesses or type of monument given.

Michigan Department of Conservation surveyor Marcus Schaaf R.L.S. #3104 sunk iron for corner while surveying in the area circa 1940. No witnesses or type of monument given.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

I-10 Found a 2" pipe in the intersection of North-South and East-West fire lanes.

14- Found a 1 1/2" pipe in the centerline of North-South fire lane.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-10 Added P.S. Cap #33981 to the found 2" pipe

Wit: Nail & Tag in W/side 4" R. Pine S28°W 50.02'

Nail & Tag in SW/side 6" R. Pine S37°E 38.91'

Nail & Tag in SE/side 6" J. Pine N43°E 48.73'

Nail & Tag in NE/side 4" J. Pine N50°W 74.91'

Ctr road intersection North 3'

14- Added P.S. Cap #33981 to the found 1 1/2" pipe

Wit: Nail & Tag in NE/side 4" Oak N53°W 94.60'

Nail & Tag in SE/side 4" R. Pine N55°E 38.91'

Nail & Tag in SW/side 6" Oak S40°E 65.05'

Ctr North-South road East 0.5'

Signed by:

Carl T. Kiiskila

Date:

8-20-07

Surveyor's Michigan License No.:

33981

