SURVEY & REMONUMENTATION

OCT 0 5 1998

4581

SECTION

STATE OF MICHIGAN LAND CORNER RECORDATION CERTIFICATE ROSCOMMON COUNTY Filing Requirement of Act 74, Mich. P.A. 1970 RECORDED For corners in 8 JUN 98 10:11 A.H. Roscommon Located in: Corner Code # ROBERT W. SMITH (County) REGISTER OF DEEDS T 22N R 1W 1. Public Land Survey M-5 R T R 2. Property Controlling R R in Section S FILE IN LIBER 3 OF LAND CORNERS Miscellaneous S R Register of Deeds Stamp & File Number Property in Sec. S , Recorded Plat 4. Lot No. 5. Private Claims 2 i, Marvin E. Myers, in a field survey on 4-23, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with 5 regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: 10 NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. 12 A. Description of original monument and accessories and/or subsequent restoration: L. 1, Pg. 119 (Norman C. Caldwell. M.S GLO - 1837 John Brink, D.S. Mon. - Post P.S. # 12018 4-18-1966) Mon. - 12" Buggy Axle In N-S fence line. Near CenterLine Firelane West. 13" White Oak S59°W 48 lks. 16" Y. Pine N23°W 109 lks. 10" N. Pine \$31°W 54.94" 15° Oak N81°W 58.74' GLO - 1848 B.F. Hail, D.S. Mon-Post 16" Oak N25°W 61.16" Wit: 8" W, Oak N30"E 14 lks Fence Post North 3.83 10" W. Pine S73"E 48 lks. L. 2, Pg. 155 Mon. - 11 Buggy Axle In N-S fence line. Near CenterLine Fireiane West. L. 8, Pg. 147 (Timothy, L. Lapham, P.S. #27595 Nov. 23, 1988) Mon. - 11 Buggy Axle In N-S fence line, and Firelane West. 10' N. Pine S31°W 54.94' 15" Oak N81°W 58.74" Nails & Tags in 16" R. Pine S25°W 55.80" 16" Oak N25°W 61.16" Fence Post North 3.83 12" Twin Oak stump N30°W 30.65" 3" White Oak N60°E 43.68" B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 11 Axie Shaft 1.0' West of North-South fence, and in centerline of old North-South road corridor. Found Cak stumps of record, they were rotten. Found nail with MDOT tag in the SE, side of a 16" Red pine S33°W 54.84'. Found nail with MDOT tag in the S, side of a 6" Oak N60°E 43.62'. Accepted as the best available evidence of the position of the Original Government Corner. Replace axle shaft with Standard County Monument. Description of monument for corner and accessories established to perpetuate locating the position of the corner: C. Mon.- Standard Roscommon County Monument. **ROSCOMMON COUNTY** Set nail in the E. side of a 4" Cherry South 2.88" **PEER GROUP APPROVAL** Set nall in the NE. side of a 4" Oak in a clump N57°W 28.75" Found nail with MDOT tag in the SE, side of a 16" Red pine S33°W 54.84" Found nail with MDOT tag in the S. side of a 6" Oak N60°E 43.62' Mary E. Men May OF MICHGANIN

MARVIN E.

MYERS

PROFESSIONAL SURVEYOR No. 31600

PALE

LICE

BER

Surveyor's Michigan License No. 31600