

APPROVED BY PEER GROUP
P.A. 345 OF 1990
SAGINAW COUNTY

1997 REMONUMENTATION PROGRAM
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED/FILED

LIBER 2028 PAGE 436

1997 OCT -3 A 8:28

MILDRED H. DODAK
REGISTER OF DEEDS
SAGINAW COUNTY, MI.

For corners in: FRANKENMUTH TWP.

SAGINAW

(County)

Located in:

Corner Code #

1. Public Land Survey

T 11N R 06E

M-10

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. Recorded Plat

5. Private Claims

I, JONATHAN M. FIELD, in a field survey on JULY 8 19 97,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1821 GLO; WAMPLER, D.S.; 25.37 CH. SET POST ON CASS RIVER; "BALANCE OF THIS MILE & SEC. 24 & 13 & PART OF 12
IN RESERVATION"

1839 GLO; MULLETT, D.S.; SET 1/4 SEC. POST; BEECH 12 S77W 26LKS., BEECH 6 N37W 48LKS.

1968 CPCO; BOLDT; SET A-10 T11N-R7E ???.' (DIST. UNREADABLE) N. OF M-10 T11N-R6E

1981 LEACH, LS#7236; LCRC L.5, PG.167; FND. 3/4" ROD; N45W 38.20' ST. SIGN POST, S45E 41.00' 36" MAPLE, N25W
11.15' P-K NAIL IN BLACK TOP, S60W 43.43' 20" MAPLE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1997 ROWE; FIELD, PS#37276; FND. 3/4" ROD 4' E. OF C/L REESE ROAD; RECOVERED 3 PREVIOUS WITNESSES WHICH
INDICATE THAT FND. ROD IS IN SAME POSITION AS 1981 LEACH LCRC CITED IN SECTION A. ABOVE

ACCEPTED FND. ROD AS A CAREFUL AND FAITHFUL PERPETUATION OF THE ORIGINAL CORNER POSITION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-10 REPLACED FND. ROD W/ 5/8" ROD & STD. REMON. CAP IN MON. BOX

N25°W, 11.92' P-K NAIL

N85°W, 46.57' NAIL IN N. FACE 20" MAPLE

S65°W, 8.85' ROAD SIGN POST

S40°E, 32.07' NAIL W/TAG #37276 IN NE FACE 36" MAPLE

N40°E, 42.98' NAIL W/TAG #37276 IN E. FACE 22" WALNUT



Signed by

Date

Surveyor's Michigan License No.

37276

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN 25, 1971

SURVEY &
REMONUMENTATION

MAR 18 1998

SECTION

REVISED MAY 14, 1976
REVISED JAN, 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993