

SURVEY & REMONUMENTATION

APR 14 1998

REMONUMENTATION SECTION

LIBER

2 PAGE 172

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in MAPLE VALLEY TOWNSHIP

Sanilac

(County)

Located In:

Corner Code #

- | | | |
|------------------------------------|----------|--------|
| 1. Public Land Survey | T9N R13E | I - 11 |
| | T R | |
| | T R | |
| | T R | |
| | T R | |
| 2. Property Controlling in Section | S T R | |
| | S T R | |
| 3. Miscellaneous Property in Sec. | S T R | |
| | S T R | |

RECEIVED FOR RECORD

97 DEC -2 AM 9:10

LIBER NO. 2 PAGE NO. 172
ESTHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, John A Milletics, in a field survey on June 28, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2			
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

- I - 11
GLO Notes
Set Post
Beech 18 N64°E 28
Beech 12 S81°W 6
- Old Survey Liber 1886 survey
by F.F. Rogers
Survey Act 132 Liber 3 Page 187
Unrecorded Survey

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- I - 11
NW Corner Section 35 T9N-R13E
Found Monu Box with 5/8" Iron bar in Place

SURVEY & REMONUMENTATION

JAN 08 1998

COMMISSION

APPROVED PEER BOARD MEETING
NOV. 26, 1997 *gm*

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- I - 11
NW Corner Section 35 T9N-R13E
Monu Box with 5/8" Iron in Place
N45°W 89.54 feet to a nail in a P.P.
N45°E 96.90 feet to a nail in a P.P.
S45°W 44.70 feet to the NE Corner of a Stone Pillar
S45°E 70.20 feet to a nail in a T.P.
S30°E 40.27 feet to a Road Sign
N70°E 49.48 feet to a Stop Sign
South 2632.32 feet to the W 1/4 Cor of Said Section(Monu Box)

Signed by John A Milletics Date Nov 11, 1997
Surveyor's Michigan License No. 25859

