

JAN 22 2001

SECTION

LIBER

3 PAGE 57

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970  
2000 REMONUMENTATION PROGRAM

RECEIVED FOR RECORD

00 NOV 29 AM 11:11

LIBER NO. 3 PAGE NO. 57  
MICHELE VANNORMAN  
REGISTER OF DEEDS  
SANILAC CO., MICHIGAN

For corners in

Sanilac

(County)

Located in:

Corner Code #

1. Public Land Survey

T11N R16E

B - 1

T R

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

Lot No. , Recorded Plat

Private Claims

2000

John A. Millettics, in a field survey on May 1, 1990, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or at the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, covered, found as expressed below:

OTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Description of original monument and accessories and/or subsequent restoration:

GLO Notes

None

Act 132 - None

L.C.R.C. Forms - None

Old Survey Liber - None

State Highway book Page 72

Unrecorded surveys - Millettics Oct 1990, Huron Surveying April 1994, Millettics May 1995

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B - 1

N 1/4 Corner Section 6 T11N-R16E

Found no evidence of corner at site - State Highway Department removed corner during construction

West 2644.72 to NW Corner Section 6

East 2658.28 to NE Corner Section 6

Accepted as best evidence

APPROVED PEER BOARD

MEETING Nov 25, 2000

*[Signature]*

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B - 1

N 1/4 Corner Section 6 T11N-R16E

1/2" Iron Bar With Cap in concrete

East 12.78 feet to the S 1/4 Cor Section 31


South 50.95 to Michigan Bell Riser Box

North 64.48 feet to a nail in a 18" Cherry

N15°E 90.85 feet to a nail in a Power Pole

West 2644.72 feet to the NW Corner Section 6

East 2658.28 feet to the NE Corner Section 6



ned by *[Signature]*

Date Nov 15, 2000

veyor's Michigan License No. 25859