JAN 2 2 2001

3 PAGE LIBER

RECEIVED FOR RECORD

RECTION

2000 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

00 DEC - 1 AM 9: 33 LIBER NO. 3 PAGE NO. 78
MICHELE VANHORMAN
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

For	COL	ners	in

1. Lot No. 5. Private Claims

Sanitac	Located in:	Corner Code #
(County)		
1. Public Land Survey	T11N R	16E B - 7
	ŤŘ	
3 Daniel Controlling	TR	
Property Controlling in Section	S T R	
3. Miscellaneous	sR_	
Property in Sec.	S TR	

_, Recorded Plat _

Register of Deeds Stamp & File Number

, 19 , in a field survey on _ do hereby state that under equirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in

onformance with regulations and rules therefore as required in the current manual of survey instructions of the Inited States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for hat the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan loard of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, ecovered, found as expressed below:

IOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

3	l F	3 (ם:	E	F		: н		I d	ı k	: 1.	M
1					\neg							
2	-	6—	- 5	,	ģ	ب	-	3			-	_
3		┝╌┤	-4		{		\vdash	-		—	-	-
4		7-		-	})	1	0—	1	1	1	2—-
5	<u> </u>	-						H		-	-	\vdash
6)	8-	1	7	1 1	6	-1	! 5—-		4	-1	3
7	<u> </u>				\dashv					-	\vdash	<u> </u>
8	1	9	2	0_	2	1	2	2-	2	3	2	4
9		_			_	_		<u> </u>	-		_	
10	-:	ļ 50—	2	_	—2	8—	2	7	 2	6	-2	5
11		 	-			_	├-	-		-	┼─	-
12	3	<u> </u>	3	2	3	3	 - 3	4	 3	5—	 - 3	6
13	L_	l					<u> </u>	1	<u> </u>	<u> </u>	1	<u> </u>

Description of original monument and accessories and/or subsequent restoration:

R - 7

GLO Notes

Hemlock 7" N05°W

Hemlock 20" S05°E

Act 132 - Liber 1 Page 485 Chope Sept 1972 - Liber 2 Page 485 Chope Aug 1976

Liber 3 Page 274 Chope July 1975

L.C.R.C. Forms - none Unrecorded Surveys - Milletics Dec 1992 - Milletics Aug 1987 - Milletics Sept 1995

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B - 7

S 1/4 Corner Section 18 TllN-R16E

Found 1/2" Iron Bar in Gravel Road Bed as recorded

West 2660.00 feet to the SW Corner Section 18

East 2667.02 feet to the SE Corner Section 18

Accepted as best evidence



Description of monument for corner and accessories established to perpetuate locating the position of the corner.

S 1/4 Corner Section 18 TllN-R16E

1/2" Iron Bar with cap in Gravel Road Bed

NO5°E 24.60 feet to a nail in a Wooden Fence Post

N50°E 79.20 feet to a nail in a Power Pole

S45°E 79.50 feet to a nail in a Power Pole

South 33.15 feet to a nail in a wooden fence post

South 33.00 feet to a 1/2" Iron Bar

East 2667.02 feet to the SE Corner Section 18

West 2660.00 feet to the SE Corner Section 18

and Milletin rveyor's Michigan License No. 25859

Nov 15, 2000 Date

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 22, 1971 REVISED MAY 14,1875

APPROVED PEER BOARD

MEETING NOV 25 2000