

JAN 22 2001

LIBER

3 PAGE 38

## SECTION

2000 Remonumentation Program

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

03 NOV 27 AM 8:56

LIBER NO. 3 PAGE NO. 38  
MICHELE VANNORMAN  
REGISTER OF DEEDS  
SAMLAC CO., MICHIGAN

For corners in

<u>Sanilac</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T12N R15E	I - 13
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp &amp; File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

2000

I, John A Milletics in a field survey on May 1, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	10		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

## A. Description of original monument and accessories and/or subsequent restoration:

## GLO Notes

Beech 18" N12°W 12.5 Links  
Beech 12" N52°E 53 Links

Act 132 - Liber 2 Page 451

Recorded Plat Liber 1 Page 8 Carson's Plat of Carsonville

L.C.R.C Forms - None

Unrecorded Surveys- Sanilac Land May 1979, Milletics Dec 1989, Milletics Dec 1993  
Milletics April 1995, Milletics Dec. 1998

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I - 13

SE Corner Section 34 T12N-R15E

Found 1/2" Iron in Monu Box

West 2642.49 feet to the S 1/4 Corner Section 34

East 2648.30 feet to the S 1/4 Corner Section 35

Accepted as best evidence



## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I - 13

SE Corner Section 34 T12N-R15E

1/2" Iron in Monu. Box

N05°W 27.45 feet to a nail in a Power Pole

North 68.70 feet to the SE Corner of a House

East 35.40 feet to a 5/8" iron in a Monu Box

S60°E 73.43 to a nail in a Power Pole

South 29.60 feet to the center of a Manhole Cover

S10°W 30.80 feet to the center of a Manhole Cover

West 2642.49 feet to the S 1/4 Corner Section 34

East 2648.30 feet to the S 1/4 Corner Section 35

APPROVED PEER BOARD  
MEETING NOV 25 2000

Signed by John A. Milletics  
Surveyor's Michigan License No. 25859

Date Nov 15, 2000