

JAN 22 2001

LIBER

3 PAGE 40

RECEIVED FOR RECORD

SECTION

2000 Remonumentation Program
 LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970

00 NOV 27 AM 8:56

LIBER NO. 3 PAGE NO. 40

MICHELE VANHORMAN
 REGISTER OF DEEDS
 SANILAC CO., MICHIGAN

For corners in

<u>Sanilac</u> (County)	Located in:	Corner Code #
1. Public Land Survey	T 12N R 15E	K - 13
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

2000

I, John A. Millettis in a field survey on May 1, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

GLO Notes

Beech 16" N39°E 40 1/2 Links

Hemlock 10" N50°W 31 Links

Act 132 - Liber 1 Page 89 I.E. Chope, Liber 2 Page 451 I.E. Chope

Liber 4 Page 157 Kay Eng.

L.C.R.C. Forms - None

Unrecorded survey - Dunn Const. Jan 1989

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K - 13

SE Corner Section 35 T12N-R15E

Found no evidence of corner removed during construction by State Highway Dept.

West 2648.27 to S 1/4 Corner Section 35

East 2654.74 to S 1/4 Corner Section 36

Accepted as best evidence

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K - 13

SE Corner Section 35 T12N-R15E

1/2" Iron Bar in pavement with cap

East 12.54 feet to the NE Cor Section 4

S45°E 64.60 feet to a nail in a Telephone Post

S50°E 41.70 feet to a stop sign

N20°W 60.10 feet to a stop sign

N40°W 88.20 feet to a nail in a Power Pole

West 2648.27 feet to the S 1/4 Cor Section 35

East 2654.74 feet to the S 1/4 Cor Section 36

APPROVED PEER BOARD
 MEETING NOV 25 2000

Signed by John A. MillettisDate Nov 15, 2000Surveyor's Michigan License No. 25859