

JAN 22 2001

SECTION

LIBER 3 PAGE 41
2000 Remonumentation Program

RECEIVED FOR RECORD

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1979

00 NOV 27 AM 8:56

For corners in

Sanilac

(County)

Located in:

Corner Code #

LIBER NO. 3 PAGE NO. 41
MICHELE VANHORMAN
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

1. Public Land Survey

T12N R15E L - 13

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, John A Millettics, in a field survey on May 1, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO Notes

Beech 20" N85°E 19 Links

Hemlock 10" N83°W 20 Links

Act 132 - Found None

Unrecorded surveys - Dunn Const. Jan 1989, Millettics March 1991

L.C.R.C Forms - None

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L - 13

S 1/4 Corner Section 36 T12N-R15E

Found no evidence of corner, removed during construction by State Highway Dept

West 2654.74 feet to the SW Corner Section 36

East 2644.27 feet to the SE Corner Section 36

Replaced from witnesses and measurement

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L - 13

S 1/4 Corner Section 36 R12N-R15E

1/2" Iron Bar in pavement with cap

East 6.27 feet to the N 1/4 Corner Section 1

North 6.0 feet to present centerline M-46

South 54.00 feet to a R/W Marker

N50°E 160.00 feet to a nail in a Power Pole

N45°W 149.70 feet to a nail in a Power Pole

West 2654.74 feet to the SW Corner Section 36

East 2644.27 feet to the SE Corner Section 36

APPROVED PEER BOARD
MEETING NOV 25 2000

pm

Signed by *John A Millettics*

Date Nov 15, 2000

Surveyor's Michigan License No. 25859