

JAN 22 2001

SECTION

LIBER 3 PAGE 58

RECEIVED FOR RECORD

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
2000 REMONUMENTATION PROGRAM

00 NOV 29 AM 11:11

LIBER NO. 3 PAGE NO. 58
MICHELE VANNORMAN
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

For corners in

Sanilac
(County)

Located in:

Corner Code #

1. Public Land Survey

T12N R16E I - 13

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

Lot No. , Recorded Plat
Private Claims

2000

John A Milletics, in a field survey on May 1, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or at the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, covered, found as expressed below:

OTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|----|----|----|----|----|---|---|---|---|---|---|---|
| 1 | | | | | | | | | | | | | |
| 2 | 6 | 5 | 4 | 3 | 2 | 1 | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | 8 | 9 | 10 | 11 | 12 | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | 17 | 16 | 15 | 14 | 13 | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | 20 | 21 | 22 | 23 | 24 | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | 29 | 28 | 27 | 26 | 25 | | | | | | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | 32 | 33 | 34 | 35 | 36 | | | | | | | |
| 13 | | | | | | | | | | | | | |

Description of original monument and accessories and/or subsequent restoration:

GLO Notes

Hemlock 22" N54°E 13.5 Links

Beech 6" N65°W 13.5 Links

Act 132 - Liber 3 Page 363 - Liber 4 Page 579

Unrecorded surveys- NW Surveying Sept 1981 - Sanilac Land Aug 1979- Milletics Oct 1987

L.C.R.C. - None

Old Survey Liber - None

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H - 13

SE Corner Section 34 T12N-R16E

Found no evidence of corner on site State Highway Department removed during construction

West 266.105 feet to the S 1/4 Corner Section 34

East 46.85 feet to the NW Corner Section 2

Accepted as best evidence



Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H - 13

SE Corner Section 34 T12N-R16E

1/2" Iron Bar with cap in concrete

East 46.85 feet to the NW Corner Section 2

N30°W 82.95 feet to a nail in a 24" Maple

N40°E 45.85 feet to a nail in a 20" Cedar

S20°E 59.40 feet to a nail in a Anchor Pole

West 266.105 feet to the S 1/4 Corner Section 34

East 46.85 feet to the NW Corner Section 2

N50°E 63.2 feet to a nail in a Power Pole

APPROVED PEER BOARD
MEETING Nov 25, 2000

97

by John A Milletics
Surveyor's Michigan License No. 25859

Date Nov 15, 2000