SUHVEY	Č.
REMONUMENT	TATION

Surveyor's Michigan License No.

APR 07 1998 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 ST. JOSEPH COUNTY REMONUMENTATION LIBER 5 PAGE 50 FOSEGION Located to: ST. JOSEPH Corner Code # STATE OF HICHIGAN ST. JOSEPH COUNTY T 6S R 12W A-12 1. Public Land Survey FILED W 1/4 COR, SEC, 31 30 DEC 97 1:17 P.H. CYNTHIA JARRATT REGISTER OF DEEDS 2. Property Controlling in Section 3. Miscellaneous Register of Deeds Stamp & File Number Property in Sec. _ , Recorded Plat 4. Lot No. 5. Private Claims 3 I, <u>DALE L. KESLER</u> in a field survey on <u>NOV. 16</u>, 19 <u>97</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Spryeyors or Ly ... Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed pelent NOTE: Not more than 2 comers, all in the same town and range, may be recorded A. Description of original monument and accessories and/or subsequent restoration: THIS CORNER WAS NOT ORIGINALLY SET. *APRIL 24, 1916 GEORGE EAGLETON. FOUND ANGLE IRON & STONE. 9" OAK N 29 E 1.00 3/4 CHAINS, 9" HICKORY N 69 1/2 E 0.57 CHAINS. RATIFIED BY PEER GROUP AUG. 1876 MOSTROM ASSOCIATES. FIELD NOTES FOUND FLAT IRON. IN ACCORDANCE WITH P.A. 348 ON Dec. 8 , 1997 CO. REPRESENTATIVE B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: CORNER WAS NOT FOUND. REESTABLISHED BY SETTING THE WEST 1/4 CORNER MIDWAY BETWEEN THE NW CORNER OF SECTION 31, T6S, R12W AND THE SW CORNER OF SECTION 31, T6S, R12W AND ON THE EAST LINE OF THE NE 1/4 OF SECTION 36, T6S, R13W, CASS COUNTY. Description of monument for corner and accessories established to perpetuate locating the position of the corner: SET 5/8" X 2' IRON ROD WITH ALUMINUM CAP IN A MONUMENT BOX. THIS POSITION WAS NOT ESTABLISHED BY ORIGINAL GOVERNMENT SURVEYORS. THIS MONUMENT IS ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE CORNER.

E 1/4 CORNER SECTION 36, T6S, R13W SOUTH 4.75'
NAIL & TAG POWER POLE N 51 DEGREES W 150.17'
NAIL & TAG POWER POLE N 56 DEGREES W 121.15'
NAIL & TAG 28" OAK S 37 DEGREES W 41.76'

THIS POSITION WAS NOT ESTABLISHED BY OF MICH.

OF MICH.

DALE L

KESLER
LANDSURYOR

LANDSURYOR

LANDSURYOR

LANDSURYOR

LANDSURYOR

ALL

LANDSURYOR

ALL

LANDSURYOR

LANDSURYO 38117 CAND SURVEYED 38117 CAND SURVEYED

EVEYORE, JAN, 28, 1971 HENDED MAY 14, 187

FORM APPROVED BY INICHBOAN STATE ADARD OR PROPERTICIONAL CURVEYO