

SURVEY &  
REMONUMENTATION

JAN 22 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1971

For Corners in

ST. JOSEPH	Located In:	Corner Code #
(County)		
1. Public Land Survey	T <u>7S</u> R <u>10W</u>	<u>J-7</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling	S _____ T _____ R _____	_____
in Section	S _____ T _____ R _____	_____
3. Miscellaneous	S _____ T _____ R _____	_____
Property in Sec.	S _____ T _____ R _____	_____
4. Lot No. _____	Recorded Plat _____	
5. Private Claims _____		

LIBER 5 PAGE 119

STATE OF MICHIGAN  
ST. JOSEPH COUNTY  
FILED

15 DEC 1998 11:19:27 AM

CYNTHIA L. JARRATT  
REGISTER OF DEEDS

Register of Deeds Stamp & Filing Number

I, DONALD C. ANDREWS, in a field survey on JUNE 4, 1998, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefor as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corners mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monument, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be Recorded on this certificate.

A. Description of original monument and accessories and/or Subsequent restoration:

GLO POST -

CO. ROAD COM. 1965 LARGE POINTED STONE IN MONUMENT BOX WIT. 26" MAPLE S42°W 47.80'R, 23" MAPLE S61°W 72.8'R

CO. SURVEYOR RECORD BOOK B, P. 452, 1911 EAGLETON, STONE BY OTHERS BEARING TREES GONE

SAYERS SURVEY 1977 FOUND PIPE IN MON BOX 1 FOOT SOUTH OF EDGE BIT. ROAD

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND ½ BY 36" PIPE IN MON. BOX 1 FOOT SOUTH OF EDGE OF BIT. ROAD. DUG DOWN 34 INCHES AND FOUND NOTHING ELSE.  
CHECKED RECORD WITNESSES: 36" MAPLE S40°W 47.30'M, AND 36" MAPLE S65°W ±72'M. GLO BEARING TREES GONE.

C: Description of monument for corner and accessories to perpetuate locating the position of the corner:

REPLACED ½ BY 36" PIPE WITH 5/8" IRON X 24 INCHES WITH STANDARD REMON. CAP IN MON. BOX

½" X 36" PIPE S 60°E 28.41'  
5" LOCUST SOUTH 17.35'  
36" MAPLE S 40°W 47.30'  
36" MAPLE S 55°W 59.82'

RATIFIED BY PEER GROUP  
IN ACCORDANCE WITH P.A. 345  
ON June 8, 1998  
Wiers CO. REPRESENTATIVE



Signed by Donald C. Andrews Date 10/28/98

Surveyors Michigan License No. 33967

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVYORS, JAN. 28, 1974  
REVISED MAY 14, 1975  
REVISED JAN., 1983  
REVISED OCT., 1995  
ADAPTED FOR WORD PROCESSING

REMONUMENTATION