SCHOOLCRAFT COUNTY PEER GROUP APPROVED

OCT 2 6 1995

DATE March 10, 1995 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

Schoolcraft (County)	Located In:	Corner Code ##	Received & Filed this 10 day of			
Public Land Survey	T <u>42N</u> R <u>15N</u> T R T R T R	E3	Sigrid 1. Hedberg Schoolcraft Co. Reg. of Deeds			
2. Property Controlling in Section	S T R S T R					
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number			
Property in Sec.	S T R		Tregister of Beeds Staffip & The Homber			
4. Lot No	, Recorded Plat					
			A B C D E F G H I J K L I			
			2 - 6 5 4 3 2 1 -			
			3 + + + + + + + + + + + + + + + + + + +			
			4 - 7 - 10 - 11 - 12-			
	, in a field survey onJan requirements of P.A. 74, Michigan P.A					
-	re in conformance with regulations ar	•	Dianian lan lan lan lan			
-	structions of the United States Depar					
	of a Court of Law and/or that the corne with the rules of the Michigan Board		ree of a			
	d, re-established, monumented, re-	• • • •				
expressed below:			10 30 29 28 27 26 25			
NOTE: Not more than 4	4 corners, all in the same town a	nd range, may be recorded	d 11			
on this certifica	ite.		12 31 32 33 34 35 36			
A Description of origin	val manument and acceptation on	id/or outpossuant rootoratio	13			
· · · · · · · · · · · · · · · · · · ·	al monument and accessories an	·				
		· -	rryweather. Original accessories: Sugar 10 N32E 14.			

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Maple \$14E 12.4', 10" Maple \$14W 15.3', 16" Beach N44W 15.9', 5" Maple N67E 11.7'".

(E3) Original post and accessories not recovered. Found no acceptable evidence of the position of the original corner on the ground. Recovered the monument placed by Wiggins in 1991, as described, in good condition, and at record bearing and distance from his accessories. Through review of the original field notes of Wiggin's survey, I determined that the 1991 corner position is erroneous, made so by a transcription error in the reduction of the field notes. This resulted in a 54 ft. error in the determination of the distance to A3, one of the corners used in the double proportion noted above. I recomputed the double proportionate position using the 1991 control, and the correct 1991 field notes and verified that the accuracy of the 1991 work was acceptable through ties to GPS horizontal control monumentation established in 1994 by the Schoolcraft County Remonumentation Program. I determined the proportionate position to be 10632.08' East of A3, 5294.99' South of E1, 5299.48' West of G3, and 2635.31' North of E4. At the position for the corner I placed the 1991 monument, being a 1°I.D.x36" iron pipe capped with a 4" diameter cast aluminum Michigan Department of Natural Resources tablet, appropriately stamped. I defaced the markings on the 1991 NBTs: 16" Maple, 10" Maple, and 5" Maple.

corners 2 miles west and original corner 1 mile east, a corner 1 mile north and a 1/4 corner 1/2 mile south. DNR monument placed. 16"

C.	Description of mor	nument for corner an-	d accessories	established to	perpetuate lo	ocating the posit	ion of the corner:
----	--------------------	-----------------------	---------------	----------------	---------------	-------------------	--------------------

(E3) Placed 1" I.D. pipe with 4" MDNR cap. Blazed, scribed, and placed measuring nails with Ref. tags in: 1) 16" Maple \$56W 18.4' "S8 NBT" 2) 16" Beech N64W 32.8' "S4 NBT" 3) 5" Maple N44W 10.3' "S4 NBT" 4) 5" Maple N79E 11.8' "S5 NBT" Cedar post with Schoolcraft Co. Survey poster is adjacent. 1) & 3) are 1991 NBTs with new markings made. 2) is 1991 NBT with old markings undefaced. Bearings magnetic.

SZYSZKOSKI LAND URVEYOR

Date

Surveyor's Michigan License No.

Signed by ___

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

For the Michigan Department of Natural Resources - Forest Management Division.

REVISED MAY 14, 1975