

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 19 T 43N R 13W	B8 (GCDB 140340)
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 04/02/14 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Center of Section 19. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Established the position for the corner at the intersection of straight lines connecting opposite
1/4 corners. The monuments for government corners B7 and C8, set in 2004 for Schoolcraft County
Remonumentation by contract surveyor Michael Peterson, were discovered to have been placed in
erroneous positions. The position for the 1/4 corner herein described was calculated using Mr.
Peterson's monumented A8 and B9 and the proper (but unmonumented as of this date) positions for B7
and C8, the position of the latter two being in accord with the method of reestablishment described
in the certificates of record, L5-P61 and L5-P65, both having been reestablished by proportionate
measurement to the original record.

C. Description of monument for corner and accessories established to perpetuate locating the position of the

Set 1"IDx36" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
6" B.Spruce S19°W 3.55' mrkd "CS BT"
6" B.Spruce N43°W 18.8' do
7" B.Spruce N33°E 11.2' do
6" B.Spruce S55°E 10.05' do
E= 8078884.724 m N= 147719.040 m



Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).
Coord. Ref.=NGS PID RJ0523: N= 146960.205 m. E= 8082759.393 m.

Signed by Stephan J. Szyszkoski Date 04/16/2014
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division