

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft	Located In:	Corner Code #
(County)		
1. Public Land Survey	T R	
	T R	
	T R	
	S T R	
2. Property Controlling	S 18 T 44N R 16W	4
in Section	S 18 T 44N R 16W	8
3. Miscellaneous	S T R	
Property in Sec.	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims	8 Dec 04 2006	
	4 Dec 02 2006	

Register of Deeds Stamp & File
Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on _____, 20____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(4-Sec. 18) Northwest 1/16 corner, Section 18. Not established in the original survey.
(8-Sec. 18) West 1/16 corner, Section 18. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(4-Sec. 18) Established the corner at the intersection of straight lines connecting opposite 1/16 corners. From the position thus established, I found an iron pipe, not of record, placed by persons unknown, S06W 15.6' distant (magnetic bearing).
(8-Sec. 18) Established the corner on a straight line between Quarter corner 1175.48' west and the intersection of 1/4 lines 1318.50' east, being 19.96' chains, proportionate to the original record, west of the Center of Section. From the position thus established, I found a 1/2" iron pipe, not of record, placed by persons unknown, S58W 23.3' distant.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(4) Set 1"IDx36" I.pipe with 4" alum. MDNR cap. Set measuring nails in: 10" J.Pine S33E 19.63' mrkd "NW1/16 BT" 12" R.Pine N46E 39.63' do 10" R.Pine N19W 39.60' do 12" J.Pine S82W 26.93' do Bearings are magnetic. Distances are to nails with tag.	(8) Set 1"IDx36" I.pipe with 4" alum. MDNR tag. Set measuring nails in: 16" W.Pine S45E 31.85' mrkd "W1/16 BT" 25" R.Pine N44E 83.43' do 5" Spruce N19W 39.63' do 7" Spruce S58W 39.05' do Bearings are magnetic. Distances are to nail with tag.
--	--



Signed by Stephan J. Szyszkoski Date 1/17/07
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Office of Land and Facilities