

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 19 T 46N R 13W	1
	S _____ T _____ R _____	(GCDB 120400)
	S 19 T 46N R 13W	8
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	(GCDB 120340)
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 08/20/14 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(1-Sec. 19) West 1/16 corner common to Sections 18 and 19. Ca. 1962-1964 - MI Dept. of Conservation personnel installed a capped 1"ID iron pipe, not stamped to identify the corner, at an erroneous position. No witnesses were made and a record of the monument was not filed with the county Register of Deeds. The original plat of this township gives distances 18.2625 chains west to Section corner and 20.0625 chains east to Quarter corner.

(8-Sec. 19) Center-West 1/16 corner, Section 19. Not previously monumented. The original plat of this township yields distances 18.42875 chains west to Quarter corner and 20.09875 chains east to the Center of Section 19.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(1-Sec. 19) Established the position for the corner on the Section line between Section corner 1169.59' west and Quarter corner 1284.94' east, proportionate to the dimensions given on the original plat. Found the MDOC marker 32.6' east of this position and removed it.

(8-Sec. 19) Established the position for the corner on a straight line between Quarter corner 1178.29' west and the intersection of 1/4 lines of Section 19 1285.06' east, proportionate to the dimensions derived from the original plat.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(1) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" B.Spruce N59°W 1.05' mrkd "W1/16 BT"
8" J.Pine N64°E 27.65' do
9" J.Pine S58°E 13.05' do
10" J.Pine S29°W 32.15' do
E= 8078055.560 N= 177340.570

(8) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
10" J.Pine S72°W 30.45' mrkd "W1/16 BT"
11" J.Pine S14°E 40.0' do
9" J.Pine N71°E 56.25' do
5" J.Pine N25°W 45.4' do
E= 8078067.465 N= 176537.128

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)
Coord. Ref.=NGS PID RJ1233: N= 183112.192 m. E= 8082067.781 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 09/04/2014

For the Michigan Department of Natural Resources, Forest Resources Division

