

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T 46N R 13W	B9
	T R	(GCDB 140300)
	T 46N R 13W	C9
	T R	(GCDB 200300)
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on B9 08/14/14
C9 08/26/14 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(B9) Quarter corner common to Sections 19 and 30. 1961 - Remonumented by Billy D. Buckler RLS from
one Y.Pine stump (probable B.T.) bearing N72°E 46 links. Stump badly burned. Set 1"ID I.pipe with
4" brass cap: 8" J.Pine N60°W 54.5 links, 8" J.Pine S01°W 50.5 links.

(C9) Corner common to Sections 19-20-29-30. 1961 - Reestablished by Billy D. Buckler RLS by double
proportionate measure from corners 1/2 mile west; 1 mile south; 1 mile north; and 1 mile east. Set
1"ID I.pipe with 4" brass cap. 10" Elm N64°E 19.5 links, 14" Cedar S43°W 104 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(B9) Found the 1961 monument in good condition and at record bearing and distance from the 1961
witnesses. The J.Pine N60°W is standing dead; the J.Pine S01°W is dead and down. Accepted the
monument as a careful and faithful perpetuation of the position of the original corner.

(C9) Found the 1961 monument in good condition and at record bearing and distance from the 1961 NBT
Cedar S43°W, in good condition. The 1961 Elm NBT was not recovered. Verified the position of the
monument to be substantially at the proportionate position of record and accepted same as a careful
and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(B9) Found 1"ID I.pipe with 4" brass MI Dept. of
Conservation cap. Set measuring nail with MDNR tag
in the side of:

9" W.Pine N82°E 99.65' mrkd "1/4S NBT"

8" R.Pine N48°W 52.3' do

5" twin R.Pine N15°W 73.45' do

9" R.Pine N15°E 65.4' do

E= 8078471.009 N= 175740.710

(C9) Found 1"ID I.pipe with 4" brass MI Dept. of
Conservation cap. Set measuring nail with MDNR
tag in the side of:

10" B.Ash N10°E 39.65' mrkd "S20 NBT"

6" Maple S26°W 41.75' "S30 NBT"

24" Cedar S49°W 68.3' "S30" (1961 NBT)

11" B.Ash S86°W 67.9' "S30 NBT"

E= 8079278.606 N= 175748.170

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)
Coord. Ref.=NGS PID RJ1233: N= 183112.192 m. E= 8082067.781 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 09/04/2014

For the Michigan Department of Natural Resources, Forest Resources Division

