

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T 46N R 14W	I1
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S 3 T 46N R 14W	H2
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4					2		1	
3													
4	7		8		9			10		11		12	
5													
6	18		17		16			15		14		13	
7													
8	19		20		21			22		23		24	
9													
10	30		29		28			27		26		25	
11													
12	31		32		33			34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on I1 04/20/2010 do hereby state

that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(I1) Corner common to Sections 2-3 T46N-R14W and Sections 34-35 T47N-R14W. 1953 - Dean C. DeLaMater RLS found the corner monumented in the original position, as determined by two original B.T.s still in place, fair condition. He found a 1 1/4" pipe with 1 1/2" brass cap at the corner position. New bearing tree: 14" R.Pine S23E 65 links.

(H2) Center of Section 3. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I1) Found a 1 1/4" iron pipe with brass cap stamped "C.C.", undoubtedly placed by Carl Christianson, date unknown, with a 1 1/2" OD I.pipe adjacent. The 1953 NBT R.Pine is in good condition with open blaze and some scribing visible. Found two additional NBTs, marked by persons unknown, blazed, scribed, with measuring nail and washer, and described below. Found remains of original Y.Pine B.T. 18" N15W 19 links, now a rotted stump. Accepted the "C.C." monument as a careful and faithful perpetuation of the position of the original corner.

(H2) Established the corner at the intersection of straight lines connecting opposite 1/4 corners. From the position for the corner a 5" Maple S78W 42.9' distant was found marked by others with blue paint for an approximate corner. Blue paint lines originate at this Maple going N,S,E.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I1) Found 1-1/4" I.pipe with brass cap "C.C."  
Set measuring nail with MDNR tag in the side of:  
18" R.Pine S12E 43.65' 1953 NBT  
14" R.Pine N13W 19.25' Found blazed/scribed  
14" R.Pine S32W 10.0' do  
20" W.Pine N83E 21.2' mrkd "S35 NBT"  
Bearings are magnetic.

(H2) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
11" J.Pine N03E 35.3' mrkd "CS BT"  
5" R.Pine N65W 67.0' do  
5" Maple S78W 42.9' do  
6" R.Pine S53E 26.9' do  
Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 12/01/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division

