LAND CORNER RECORDATION CERTIFICATE 2000 REMONUMENTATION PROGRAM

Filing Requirement of Act 74, Mich. P.A. 1970

SURVEY & MONUMENTATION

JAN 1 6 2001

SECTION

For corners in	1	SECTION					
SHIAWASSEE	Located in: Corner Code) 1984H 00100 HANDI		i i ((00))); ea		2011100	
(County)	Venice Twp.					3044408 Page: 1 12/04/20	of 1 00 09:53A
1. Public Land Survey	T <u>7N</u> R <u>4E B-5</u> TR	Kaye Grubba - S	hiawassee C	o. REMO		L-1 P-3	48
2. Drawnin Ounter III	T R		ister of De		p & File N	umber	
2. Property Controlling Sin Section S 3. Miscellaneous S Property in Sec. S	T R T R T R T R T R T R T R T R T R T R	APPR County Remoi	DVE Dumentat	D Poor ion			
		Peer Revie	w Group	C D E	FGI	4 1 3 4	(L M
4. Lot No, Recorded Plat 5. Private Claims			2 6	5		} 2	
			3 - 7		0 1		
do nereby certify that under requiremen	n a field survey on November 09 nts of P.A. 74, Michigan P.A. of 1970, the	20 00 ,	5	-		0 11	12
Current manual of survey instructions of	Mance with regulations and rules then If the Linited States Department of the L	efore as required in the	6 18	17	16 1	5 14	13
above were in conformance with the rul Court of Law; established, re-estab	of Law and/or that the corner points on the less of the Michigan Board of Land Surv.	manne or he a Donne of a	8 19	20	21 2	2 23	24
expressed below:			9 30	29	28 2	7 26	25
NOTE: Not more than 4 corners on this certificate.	s, all in the same town and range	, may be recorded	11 31	32	33 34	4 35	36
	•		13	92	33 3	• 33	30
A. Description of original n	nonument and accessories ar	nd/or subsequent re	storation:				·
B-5 1/4 Corner common to Sections 7 &18, T7N-R4E, Venice Township, Shiawassee County 1822 GLO notes by J. Wampler, D.S. Set wood post, witnessed by S80W 19 lks (12.54') 10" Tamarack, S72E 29 lks (19.14') 8" Tamarack, B-5 to A-5 = 53.25 ch (3514.5'), B-5 to C-5 = 40 ch (2640')							
No subsequent record of r	restoration or perpetuation.						
	r						
							1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
		:				٠.	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:							
B-5 1/4 Corner common to Sections 7 &18, T7N-R4E, Venice Township, Shiawassee County Found no evidence of the original government corner or accessories. Found wood fence corner post which falls 4.3'±							
South of a line from C-5	to A-5 and approximately 8'± West 1/8 corner on the section	Nest of a single prope	ortionate n	osition to	GIO me	acrina A	fonno
this same line. We calc	culated a position using the E-W ion would fall approximately 4.3	/ position of the N-S f	ence line r	innina ec	udh on s	line bet	1000
C= C-A of C-B Defluesian	3495.62 (GLO = 3514.5) and B	-5 to C-5 = 2639 97' (Gi () = 284	M) Wa	DOCOMB	and area	epting
are conculated position a	as a careful and faithful re-estab	AISOURIEUT OF THE POSITION	on or the o	nginai go	vemmer	it comer.	
C. Description of monumen	t for comer and accessories	established to perpo	etuate loca	ating the	positio	of the c	omer:
Set standard Shiawassee (Cuons 7 &18, T7N-R4E, Venice Tow County Hamison monument and Ca	Mishin. Shiawassee Co	ıntv			7 1 1	
East 6.15' Set nail/F	b of Carsonite post Rowe tag N. face 14" tree	The state of the s	7.5	-		-	
East 14.45' Set nail/F South 4.41' Set nail/F	Rowe tag N. face 14" tree Rowe tag E. face 8" comer fence g	07 N1C/1					
		JACK N. OWENS	N. S.			-	
Signed by	Iwal :	PROFESSIONAL SURVEYOR	1 2 2	Date	11/	17/20	50
Surveyor's Michigan License No.	20709	No. 20709	TONED BY	NCHIQAN STATE	BOARD OF LAN	D SURVEYORS, J	MM. 26, 5971 BAY 14, 1978