

**SURVEY &  
REMONUMENTATION**

MAR 05 1998

**SECTION**

1997 REMONUMENTATION PROGRAM

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Kingston Township

<u>Tuscola</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T12N R11E	F-13
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

RECEIVED FOR RECORD  
LIBER NO. \_\_\_\_\_ PAGE NO. \_\_\_\_\_  
FILE NO. #165  
97 NOV 12 PM 3:47  
TUSCOLA COUNTY  
REGISTER OF DEEDS  
**COPY**  
Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Kenneth D. Dunton, in a field survey on Sept. 28, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

**A. Description of original monument and accessories and/or subsequent restoration:**

March 18, 1834 Hervey Parke, D.S. Set quarter section post. Birch 14" N66°W 8 links, Elm 14" N54°E 18 links. Aug. 1, 1963 M.S.H.D. witness card, Donald C. Pyle, R.L.S. #3165, set P.K. nail & cap in conc. under bituminous pavement. N56°W 61.02' 15" Maple, N04°E 51.18' p.p., S68°W 83.33' 14" Maple, S37°E 39.71' 14" Maple. April 24, 1973 survey L-433, P-166 & 167 by Rowe, L.S. #11192. Chiseled "+" in pavement. N45°E 22.40' lt. edge of metal, S45°E 21.10' rt. edge of metal, S70°W 53.95' rt. edge of metal. Oct. 25, 1973 survey L-436, P-254 by Rowe, L.S. #11192. Chiseled cross in pavement. Accessories same as survey L-433, P-166 & 167. Sept. 23, 1981 survey L-520, P-312 & 313 by Fokens, L.S. #21567. No mention of object or accessories.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

Found 1/2" iron rod in monument box and two accessories that indicate the corner found is in the same relative position as the 1973 survey L-433, P-166 & 167. Accepted 1/2" iron rod as the best evidence of the original corner.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

Placed standard brass cap over 1/2" rod found in monument box. Stamped cap F-13, T12N-R11E. Encased cap & rod in concrete in monument box. N30°W 64.25' top center of fire hyd. North 75.10' S. face conc. R/W marker. North 0.15' E-W centerline conc. pavement M-46. N56°E 21.65' lt. edge conc. pavement at sta. 9+13 (pave. joint). S58°E 21.70' rt. edge conc. pavement at sta. 9+13 (pave. joint).

Signed by [Signature]  
Surveyor's Michigan License No. 23503

Date 11-10-97

APPROVED  
11-10-97  
[Signatures]



