

MAY 05 1997

COMMISSION

For corners in N. Akron Twp.

1996 REMONUMENTATION PROGRAM  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD  
JAN 10 1997  
FILE NO. N. Akron Twp.  
56 DEC 26 PM 3:39

Tuscola (County)	Located In:	Corner Code #
1. Public Land Survey	T15NR 8E	I-13
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Kenneth D. Dunton, in a field survey on June 30, 1996, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. 1821  
Joseph Wampler, D.S.  
Set post corner Secs. 34 & 35  
in mound.  
No accessories.

April 27, 1898 Survey by John A. Teskey,  
County Surveyor of Section 2, T14N-R8E  
Notes indicate NW Cor. Sec. 2 set by South  
Corner 34 & 35, T15N-R8E. No distance given  
between corners. No accessories.

Note: Section A continued on back of form.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found nothing. Re-established corner proportional to 1906 resurvey of  
Section 34 by L. M. Brumley.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed 5/8" rod and standard brass cap stamped Corner I-13, T15N-R8E.  
Placed monument box over rod & cap.

N17°E 37.50' SW corner of North headwall.  
N40°E 48.65' SE corner of North headwall.  
S21°E 39.41' NW corner of South headwall.  
S37°E 45.85' NE corner of South headwall.  
N85°W 33.47' fnd. 1" iron bar in mon. box Apparent Cor. I-1, T14N-R8E.  
North 2.8'± physical centerline E-W asphalt pavement.  
East 28'± centerline of Tuttleville Drain to North (not centerline box culvert)

Signed by [Signature]  
Surveyor's Michigan License No. 23503

Date 12-9-96

APPROVED  
12-9-96  
[Signature]

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983  
REVISED OCT., 1995

April 12-18, 1906 Survey by L. M. Brumley, County Surveyor of Section 34, T15N-R8E.

Wedge shaped stone surrounded by stones & crockery at corner.  
Maple 9 N 54 3/4 E 66 1/2; Maple 9 S 49 3/4 W 1.35 1/4

April 1937 minutes of survey of the Tuttleville Drain by Roscoe J. Black, County Drain Commissioner.  
County Drain book 32, Page 413.

The SW cor. Sec. 35, T15N-R8E is 12' West of where the centerline of the drain intersects the South line of Section 35.

