

RC 1519

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

L127797PA682

For corners in

WAYNE

(County)

Located In:

OTHER
Corner Code #

1. Public Land Survey

T 1 S R 13 E

010

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Compliance with
ACT 345, P.A. 1990

APPROVED ON: 11-21-94
WAYNE COUNTY REMONUMENTATION
PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number

RC 1519

4. Lot No. , Recorded Plat

5. Private Claims POINT COMMON TO P.C.'S 618 & 619 AT SOUTH LINE OF MACK AVE.

I, MARTIN C. DUNN, in a field survey on DECEMBER 13, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

NO CORNER SET IN ORIGINAL GOVERNMENT SURVEY

PLATS

L. 59 P. 63-64 GROSSE POINTE COUNTRY CLUB WOODS
L. 60 P. 16 GROSSE POINTE COUNTRY CLUB WOODS NO. 1
L. 67 P. 95 GROSSE POINTE COUNTRY CLUB WOODS NO. 2
L. 68 P. 89 COLONIAL FARM'S SUBDIVISION
L. 70 P. 37 BLOSSOM LANE SUBDIVISION
L. 71 P. 34 COLONIAL FARM'S SUBDIVISION NO. 2
L. 73 P. 32 COLONIAL FARM'S SUBDIVISION NO. 3
L. 73 P. 92 COLONIAL FARM'S SUBDIVISION NO. 4

APRIL 3, 1926
MAY 19, 1926
NOVEMBER 28, 1940
OCTOBER 3, 1941
MAY 4, 1946
JULY 29, 1948
OCTOBER 3, 1951
AUGUST 21, 1952

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

HELD FOUND MONUMENT. (NOT IN PAVEMENT)

VERIFIED LOCATION WITH OTHER FOUND MONUMENTS.

PLACED WAYNE COUNTY REMONUMENTATION MARKER AND ALUMINUM CAP #30081 ON EXISTING MONUMENT.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

WAYNE COUNTY REMONUMENTATION MARKER AND ALUMINUM CAP #30081 ON EXISTING MONUMENT.

WITNESSES

AZ. 110° 20.00' SET PK WITH TAG IN SOUTH FACE OF UTILITY POLE
AZ. 112° 19.05' SET PK WITH TAG IN NORTH FACE OF 12" OAK
AZ. 250° 20.95' SET PK WITH TAG IN CONC BACK OF CURB
AZ. 290° 8.60' SET PK WITH TAG IN SOUTH FACE OF UTILITY POLE

THE SELECTED LOCATION FOR THIS PROPERTY CONTROLLING MONUMENT IS ACCEPTED AS A CAREFUL AND FAITHFUL DETERMINATION OF THE POSITION AS INDICATED.

Signed by Martin C. Dunn Date 12/22/94

Surveyor's Michigan License No. 30081

