RECORDED WASHTENAW COUNTY. M

SURVEY & REMONUMENTATION

MAR 0 9 1998

RECORDED WASHIENAW COUNTY, MI

Jan 22 8 32 AM *98

SECTION

Jan 22 8 32 AM 198

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 EGG COUNTY OF THE COUNTY O

For corners in			- Copy -
Washtenaw (County)	Located In:	Corner Code #	
1. Public Land Survey	T <u>2S</u> R <u>5 E</u> T R T R		-Сору-
2. Property Controlling in Section3. Miscellaneous Property in Section	S T R S T R S T R		Liber 00002 Page 0068 RM Register of Deed Stamp & File Number
4. Lot No, R	ecorded Plat		A B C D E F G H I J K L M

I, Thomas L. Sutherland, in a field survey on 11/6, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- 3 4 5 18 17 15 6 16 13 7 20 24 8 2.1 23 9 29 26 25 30 28 27 10 11 31 32 33 12 13
- A. Description of original monument and accessories and/or subsequent resortation:

G.L.O. 1819, Field Notes

5. Private Claims

1) 4" Aspen S75ºE 11 Links

H.H. Atwell, #322, No Date, Grid Book

- 2) 26" Burr Oak East 23.8
- 3) 24" Burr Oak S51ºE 28.1
- 4) 16" Burr Oak S161/2°W 75.0

Atwell-Hicks, 1/30/56, Field Notes, Iron Rod

Atwell-Hicks, R. Jagow #6998, 12/3/73

L.C.R.C., Liber 3, Page 321

1/2" Iron Pipe

- 34" Burr Oak East 23.9 2)
- 3) 36" Burr Oak S51ºE 28.1
- 32" Burr Oak S16°W 74.8
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found 1/2" Iron Rod at surface of asphalt 3.8 Feet West of Centerline Stripe over 1" Iron Pipe and bricks 18" below surface. Reset 3/4" x 18" Iron Pipe with Aluminum Remonumentation Cap Stamped 24620 in Monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" x 18" Iron Pipe with Aluminum Remonumentation Cap Stamped 24620 in monument box.

- 2) 39" Oak East 23.90 to Remon Tag on Easterly Side
- 39" Oak S51°E 28.10 to Remon Tag on Southwest Side 3)
- 34" Oak S16°W 74.80 to Remon Tag on Easterly Side Power Pole N40°W 57.77 to Remon Tag on Southwest Side 18" Oak N40°E 85.21 to Remon Tag on Northwest Side Concrete Monument A-5, T2S, R6E North 243.98

APPROVED DATE 12-2-97 CO. REP.

field observation, that this corner is accepted as the best available evidence I conclude after careful study of the record documentation and OF MICHIE position of the original corner.

Signed by: Surveyor's Michigan License No. THOMAS L LITHERLAND

12-4-97