



M-12, T2S, R7E

LIBER

1 PAGE 248 Rn

- Copy -

- A. No date Lloyd W. Fall Survey  
"Stone" shown on survey drawing 23.65 south of W 1/4 cor. Sec. 31  
Canton Twp

3-18-1980 Washtenaw Eng. L.C.R.C. L. 6, P. 16

Found bent 3/4" iron pipe. Replaced with 1/2" iron pipe

- |               |       |               |
|---------------|-------|---------------|
| 1) 2" Spruce  | EAST  | 17.2          |
| 2) Power pole | N05°E | 21.53 to nail |
| 3) 16" Oak    | S85°W | 42.97 to nail |
| 4) 4" Ash     | N15°E | 52.29 to nail |

- C. Found 1/2" iron pipe w/brick pieces. Set 1" x 2' I.P. w/ remon.  
cap over 1/2" I.P.

- |                   |       |                               |
|-------------------|-------|-------------------------------|
| 1) 6" Spruce      | EAST  | 17.23 to nail w/W.C.R. tag    |
| 2) Power pole     | N05°E | 21.62 to nail w/W.C.R. tag    |
| 3) 18" Oak        | S85°W | 42.66 PK to nail w/W.C.R. tag |
| 5) 8" Elm         | N55°W | 34.38 PK to nail w/W.C.R. tag |
| 6) 3/4" iron pipe | NORTH | 24.08                         |
- 0.15 East of E-line  
Section 36

APPROVED

DATE 12/5/94

CO. REP. H