SURVEY & REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

NOV 0 2 1000

For corners in	-		940	" "
VASHTENAV	Located In: Co	orner Code #	ير يوست.	الماريخ والمتواطع والمتواطع والمتواطع والمتواطع والمتواطع
(County)	SHARON TOWNSHIP		5	ECTION
1. Public Land Survey	T <u>3S</u> R <u>3E</u> TR TR	K-6		" 04 " 04
Property Controlling in Section Miscellaneous Property in Sec.	TR S TR S TR S TR S TR	Peggy M. Haines	Washtenaw Co. CORREM Register of Deeds S	5017311 Page: 1 of 2 02/25/1999 02:59P L-2 P-188 Stamp & File Number
4. Lot No. Record	ded Plat			•
5. Private Claims			ABCDEF	GHIJKLI
			2 6 5 4	
I 5314 12 004 11 11 11 11 11 11 11 11 11 11 11 11 11			3	
requirements of P.A. /4, Michigan	D P.A. Of 1970 , the corner points r	28_, 19_98 do hereby state that under nentioned in lines 1 and 2 above were in	1	10-11-12-
Conformance with regulations and I United States Department of the Ir	rules therefore as required in the cu sterior. Bureau of I and Managemer	irrent manual of survey instructions of the		
mentine conner points mentioned i	in lines 3. 4 and 5 above were in co	in or by a decree of a court of Law and for informance with the rules of the Michigan stablished, re-established, monumented,	6 -19 -17 -16-	15 14 0-13
recovered, found as expressed belo	ow:	tablished, re-established, monumented,	8 19 20 21	22 23 24
NOTE: Not more than 2 come	ers, all in the same town and ran	ge, may be recorded	9	
on this certificate.		- , ,	10 30 29 28	27 26 25
			11	
			12 31 32 33	34 35 36
A. Description of original mon	nument and accessories and/or	r subsequent restoration:	13	
POPLAR 4" S 16" POPLAR 4" N 34" 1854 SURVEY OF S	'E 19 LINKS (2) (GONE) SECTION 14 BY RUSSFI WI			
W. DAK 12° N 20°E W. DAK 12° S 89°W	1.09 CHAINS (3) (GINE)			
CONTINUED ON BA				
 B. Description of corner evide 	ence found and/or method app	lied in restoring or reestablishing cor	ner:	
MINCELLITORS AND	ID ROD CAPPED WITH A P S USING IN THE 1970S. WI G IRON. MONUMENT BOX IS	RESSED 1 1/2" BRASS TOP, THI E BORED OUT AN ALUMINUM REN IN GOOD CONDITION.	S IS SIMILAR TO WHAT MONUMENTATION CAP TO	•
THE SELECTED LO BY PROFESSIONAL THE ORIGINAL COR	SURVEYURS AS THE REST	THE CONTRACTOR AND IS GENER FAVAILABLE EVIDENCE OF THE	RALLY ACCEPTED E POSITION OF	

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

	CORNER OF SECT			
FOUND ROD	WITH BRASS CAP	SET IN MONUME	NT BOX IN	ASPHALT ROAD.
	REMONUMENTATION		RON,	

N 63*E S 57*E

CO. REP.

71.42 N.W. CORNER OF HOUSE (6)
51.7 (51.50 MEAS) S.W. CORNER OF HOUSE (7)
93.95 S.W. CORNER OF GARAGE (8)
41.59' 22' ELM WITH NAIL & REMON. TAG IN S-SIDE
60.59' 14' DAK WITH NAIL & REMON. TAG IN S-SIDE
43.45' 30' MAPLE WITH NAIL & REMON. TAG IN N-SIDE
37.19' 36' TWIN CHINESE ELM WITH NAIL & REMON TAG IN S-SIDE 70°W 27°W 75°E 72°E

REO LAND SA

[] 0// 1	/ .		""11	William Comment	
Signed by TaulUSc	hvenner	Date	12-07-1998		
Surveyor's Michigan License No	29618			100	
•	DATE 12-14-98	FORM APPROVED BY A	MICHIGAN STATE BOARD OF PR	OFESSIONAL S	

REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995

A

5\8\68 VASHTENAV ENGINEERING SURVEY DRAWING SHOWS CORNER ON JOB NO. 2617 AS A FOUND IRON PIPE (5)

4/14/1972 WASHTENAW ENGINEERING SURVEY JOB NO. 7996 4\14\1972 WASHIENAW ENGINEERING SONTE FOUND 1' IRON PIPE (5) N 39°E 71.42 N.W. CORNER OF HOUSE (6) N 63°E 51.70 S.W. CORNER OF HOUSE (7) S 57°E 93.95 S.W. CORNER OF GARAGE (8)

SURVEY & REMONUMENTATION

NOV 02 1999

SECTION

4\12\1972 ACT 74 RECORDED IN LIBER 1, PAGE 679

FOUND 1' IRON PIPE (5)
N 39°E 71.42 N.W. CORNER OF HOUSE (6)
N 63°E 51.70 S.W. CORNER OF HOUSE (7)
S 57°E 93.95 S.W. CORNER OF GARAGE (8)

9\6\72 AMERICAN ENGINEERING COMPANY SURVEY DRAWING FOR PHILIP GENTILE SHOWS CORNER WITH NO WITNESSES.

11\01\72 WASHTENAV ENGINEERING SURVEY JOB NO. 9390, RECORDED IN L.1430, P.975 FOUND 1' IRON PIPE (5)
N 39°E 71.42 N.W. CORNER OF HOUSE (6)
N 63°E 51.70 S.W. CORNER OF HOUSE (7)
S 57°E 93.95 S.W. CORNER OF GARAGE (8)

12\7\1972 VASHTENAV ENGINEERING SURVEY JOB NO. 9224, RECORDED IN L.1421, P.975 12\7\1972 WASHIENAW ENGINEERING SONTE FOUND 1' IRON PIPE (5) N 39*E 71.42 N.W. CORNER OF HOUSE (6) N 63*E 51.70 S.W. CORNER OF HOUSE (7) S 57*E 93.95 S.W. CORNER OF GARAGE (8)

11\1\73 WASHTENAW ENGINEERING SURVEY JOB NO. 10058, RECORDED IN L.1461, P.795 FOUND 1' IRON PIPE (5)
N 39°E 71.42 N.W. CORNER OF HOUSE (6)
N 63°E 51.70 S.W. CORNER OF HOUSE (7)
S 57°E 93.95 S.W. CORNER OF GARAGE (8)

11\5\1973 WILLIAM LUKEY SURVEYOR SURVEY DATED 11\05\73
SHOWS THE CORNER WITHOUT ANY WITNESSES, RECORDED IN L.1464, P.908

6\9\1979 WASHTENAV ENGINEERING SURVEY JOB NO. 16864

FOUND 1' IRON PIPE IN MONUMENT BOX (5)
N 39°E 71.42 N.W. CORNER OF HOUSE (6)
N 63°E 51.70 S.W. CORNER OF HOUSE (7)
S 57°E 93.95 S.W. CORNER OF GARAGE (8)

6\13\91 WASHTENAW ENGINEERING SURVEY JOB NO. 23396

FOUND 1' IRON PIPE IN MONUMENT BOX (5)
N 39°E 71.42 N.W. CORNER OF HOUSE (6)
N 63°E 51.70 S.W. CORNER OF HOUSE (7)
S 57°E 93.95 S.W. CORNER OF GARAGE (8)

3\22\1993 WASHTENAW ENGINEERING SURVEY JOB. NO. 24375, RECORDED IN L.2769, P.161

FOUND 1" IRON PIPE IN MONUMENT BOX (5)
N 39°E 71.42 N.W. CORNER OF HOUSE (6)
N 63°E 51.70 S.W. CORNER OF HOUSE (7)
S 57°E 93.95 S.W. CORNER OF GARAGE (8)

5017311 Page: 2 of 2 02/25/1999 02:59P - Washtenaw Co.

CORREM L-2 P-189