



LIBER

1 PAGE

6Bm

- COPY -

Paragraph A. Continued:

Washtenaw Engineering Co., Inc. April 11, 1967

Allen R. Renischler, PS#15411

Found Iron Pipe 30" below road surface, raised with a 1" Iron Pipe

B. Walnut S32deg. W 57.9

NW cor. of Church S32deg. W 241.25

NE cor. of House S42deg. W 137.8

SE cor. of Block Porch N40-1/2deg. W 84.25

24" Pine S45deg. E 68.0

Atwell-Hicks, Inc. February 20, 1973

Robert J. Jagow, PS#6998

Found 1/2" Iron Pipe

B. Walnut S32deg. W 57.9

SE cor. of Block Porch N40-1/2deg. W 84.25

24" Pine S45deg. E 68.0

12" Pine N17deg. W 70.3

48" Maple S24deg. W 106.0

Washtenaw Engineering Co., Inc. 1973

John E. Oliver, PS#19840

Found 1" Iron Pipe

15" Walnut S32deg. W 57.9

NW cor. of Church S32deg. W 241.25

NE cor. of House S42deg. W 137.8

SE cor. of Block Porch N40-1/2deg. W 84.25

24" Norway Spruce S45deg. E 68.0

10" Maple N25deg. W 57.0

12" Maple N76deg. W 99.0

Atwell-Hicks, Inc. October 13, 1981

Book 799, Page 20

Found 3/4" Iron Pipe

16" Walnut S32deg. W 57.9

NW cor. of Church S32deg. W 241.25

NE cor. of House S42deg. W 137.8

14" Maple N74deg. W 98.9

1990

Found 3/4" Iron Pipe

20" B. Walnut S32deg. W 57.71(Nail SE/S)

NW cor. of Church S32deg. W 241.25

NE cor. of House S42deg. W 137.8

Utilit Pole N32deg. W 47.28(Nail E/S)

APPROVED

DATE 4/5/94

CO. REP.   A