

SURVEY &
REMONUMENTATION

MAY - 1 1995

COMMISSION

For corners in

Washtenaw

(County)

Located In:

Corner Code ##

1. Public Land Survey

T 4S R 7E

K-7

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Thomas L. Sutherland in a field survey on December 12, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(W.C.R.C. 1932)

Found 2 old wood stakes.
Re-set with Iron Pipe,
Stones and Bricks
4 Right-of Way Pipes

(Atwell-Hicks 1974)

Iron Pipe
MBT Co. Box N50°W 58.7
MBT Co. Box S45°W 71.3
Utility Pole S30°E 85.0
Utility Pole N45°E 45.7

(Washtenaw Engineering 1978)

Fence Corner N45°W 46.7
MBT Pole N45°E 45.9
Street Sign S45°W 34.05
D.E. Pole S35°E 84.9

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/4" Iron Pipe
inside of a 1 1/2"
Iron Pipe in a Monument
Box. Set an aluminum
Washtenaw County
Remonumentation
Cap over existing 3/4"
Iron Pipe and Re-Witnessed.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" Iron Pipe with an Aluminum Washtenaw County
Remonumentation Cap inside Monument Box
1 1/2" Iron Pipe N45°W 47.10
1 1/2" Iron Pipe N45°E 46.28
1 1/2" Iron Pipe S45°E 46.75
MBT Box N50°W 58.7
MBT Box S45°W 71.3
Utility Pole S30°E 85.00 to Nail W/W.C.R. Tag in W. Side
Utility Pole N45°E 45.70 to Nail W/W.C.R. Tag in S.E. Side
R.R. Tie Fence Corner N44°W 47.39 to Nail of W/W.C.R. Tag in NE Side
10" Pine S50°E 55.70 to Nail W/W.C.R. Tag in SW Side
Center of Hydrant S50°W 43.21

I conclude that after careful study of the record documentation and field observations, that this corner is a careful and faithful perpetuation of the position of the original corner.

Signed by Thomas L. Sutherland
Surveyor's Michigan License No. #24620

Date

December 16, 1994