

**SURVEY &
REMONUMENTATION**

MAY 05 1997

COMMISSION LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Baraga (County) Located in: _____ Corner Code # _____

1. Public Land Survey	T <u>51N</u> R <u>33W</u>	<u>B-7</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

RECEIVED FOR RECORD THIS 30TH DAY OF JULY 1996 AT 10:30 A.M. AND RECORDED IN LIBER 4 OF LAND CORNER RECORDATION RECORDS ON PAGES 627 - 628.

Theresa J. Schillard
BARAGA COUNTY REGISTER OF DEEDS
Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

A	B	C	D	E	F	G	H	I	J	K	L
2	6	5	4	3	2	1					
3											
4	7	8	9	10	11	12					
5											
6	18	17	16	15	14	13					
7											
8	19	20	21	22	23	24					
9											
10	30	29	28	27	26	25					
11											
12	31	32	33	34	35	36					
13											

I, Michael Mileski, in a field survey on July, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
B-7; One-quarter Corner common to Sections 18 and 19, T51N, R33W;

See back of form.

APPROVED LAND CORNER
P.A. 345 OF 1990
Baraga County
[Signature]
7-10-96

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
B-7; One-quarter Corner common to Sections 18 and 19, T51N, R33W;

Recovered the BLM monument and all accessories as described in Part A. From this monument a hemlock stump hole bears S46°W a distance of 27 lks. and a cedar stump bears N31°E a distance of 12 lks. as stated by the BLM. I left the BLM monument in place and stamped the cap "PA 345 1996". Accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
B-7; One-quarter Corner common to Sections 18 and 19, T51N, R33W;

See back of form.



Signed by *Michael Mileski* Date 12 July 1996
Surveyor's Michigan License No. 39091

A. Description of original monument and accessories and/or subsequent restoration:

B-7; One-quarter Corner common to Sections 18 and 19, T51N, R33W;

Originally established during U.S. Survey conducted by Harvey Mellen, D.S. in 1845 and monumented with a maple post witnessed by a

Hemlock 14 S46°W 27 lks. and a Cedar 12 N31°E 12 lks.

During the course of a survey conducted by Stephen Douglas of the Bureau of Land Management from 10 May 1984 to 10 November 1984 and approved 23 September 1985, this corner was remonumented with a 2½" x 30" aluminum pipe with cap stamped as to location from the remains of both U.S. bearing trees. Specifically, the BLM field notes state that from the monument " a decayed cedar stump, 15 ins. diam., bears N31°E, 12 lks. dist., the fallen trunk alongside has no mks. visible" and " a decayed hemlock stump, size indeterminate, bears S46°W, 27 lks. dist., with no mks. visible". The BLM noted the following new bearing trees:

Hemlock 15 S16°W 27 lks. (17.82')
Presently alive and 22" in dia. having a partially open lower blaze with scribing visible.
Set 7" spike E/side Measured S08°W 17.82'

Hemlock 10 N44°W 95½ lks. (63.03')
Presently alive and 16" in dia. having a healed lower blaze.
Set 7" spike NE/side Measured N50°W 62.28'

C. Description of monument for corner and accessories established to perpetuate locating the position:

B-7; One-quarter Corner common to Sections 18 and 19, T51N, R33W;

Found 2½" dia. aluminum pipe with 3" aluminum cap appropriately stamped as to location as set by the BLM in 1984.

Set 7" spike	S/side	16" Red Maple	S73°E	36.89'
Set 7" spike	S/side	22" Hemlock	S69°W	48.66'
Set 7" spike	W/side	17" Sugar Maple	N04°W	24.30'
		Location Post	N30°W	1.0'

All of the above new bearing trees are marked with upper and lower blazes, scribed "NBT", and painted red.

The following new bearing trees were established by the BLM in 1984. The condition of each is described in Part A.

Set 7" spike	E/side	22" Hemlock	S08°W	17.82'
Set 7" spike	NE/side	16" Hemlock	N50°W	62.28'

The above BLM new bearing trees were painted red.

**SURVEY &
REMONUMENTATION**

MAY 05 1987

COMMISSION