

Re-Mon. Liber 2, Page 5

1999 REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For Corners in

<u>Huron</u> (County)	Located in:	Corner Code #
1. Public Land survey: Lake	T 18_N_ R 11_E	B-13
	T _____ R _____	C-13 ✓
	T _____ R _____	
	T _____ R _____	
2. Property Controlling in Section	S _____ T _____ R _____	
	S _____ T _____ R _____	
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	
	S _____ T _____ R _____	
4. Lot No. _____, Recorded Plat _____	SECTION _____	
5. Private Claims _____		

RECORDED

Dec 28 4 18 PM '99

Francis M. McLaughlin
REGISTER OF DEEDS
HURON COUNTY, MICHIGAN
Register of Deeds Stamp & File Number

I, James T. Meek, in a field survey on October 30, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules thereof as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
Original survey, South Bdy. T18NR11E, 1835, Harvey Parke D.S.

B-13 South ¼ Corner of Section 31
Post
Elm 26", N55½°W, 17 links
Lynn 12", N70°E, 19 links

C-13 Corner of Sections 31 and 32
Post
Cedar 11", N82°E, 14½ links
Cedar 8", N56°W, 3 chains

County Surveyor's Record: none
Recorded Surveys: none
LCRC: none

County Surveyor's Record: none
Recorded Surveys: L5, P232
LCRC: none

B Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-13 South ¼ Corner of Section 31
Found ¾" iron in mon box
Accepted as the best available evidence of the original corner position.

C-13 Corner of Sections 31 and 32
Found no evidence of the original corner position
Set ½" iron w/cap #39089 in mon box based on Liber 5, Page 232, Huron County Records

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-13 South ¼ Corner of Section 31
¾" iron in mon box
From which:
Do Not Pass sign post bears N10°W, 19.5'
½" iron bears N45°E, 33.0'
No Passing Zone sign post bears S10°W, 19.4'
½" iron bears S45°W, 26.0'

C-13 Corner of Sections 31 and 32
½" iron w/cap #39089 in mon box
From which:
¾" iron in mon box bears East, 52.14'
West leg direct. sign bears N45°E, 61.8'
Tag in PP bears S35°E, 43.2'
½" iron bears N70°W, 42.0'

Signed by [Signature]
Surveyor's Michigan License No. 39089

Date 12-21-99

APPROVED AT PEER BOARD MEETING 12-16-99 RLB

