

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF--	(IRON COUNTY) LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. 41 N. R. 32 X. S. W.	I-5
2. PROPERTY CONTROLLING IN SECTION 10 _____	T. 41 N. R. 32 X. S. W.	16
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. R. _____ E. S. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 28, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

**A. Description of original monument and accessories and/or subsequent restoration:**

**Corner I-5 (Section Corner 10, 11, 14, & 15, T41N, R32W):**  
 Hemlock post (Not found. See B for subsequent monument.)  
 Cedar 14 S31E 22 (Not found. No subsequent accessories found.)  
 Cedar 10 S50W 32 (Not found. No subsequent accessories found.)

**Corner 16 (East 1/16 corner between Sections 10 & 15, T41N, R32W):**  
 Not established in original survey nor subsequently, apparently.

**B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:**

**Corner I-5:** Restored proportionately on line between probable original line tree stumps N89°46.1' E 50.863 ch. and S89°46.1' W 8.514 ch., believing this to be the best way of locating the original corner position, as the original E & W sec. line in both directions from this corner was originally run as a true line originating at this corner. Distances to river east and west on the aforementioned bearing agree almost exactly with the original record. Found a 4" x 4" x 5' squared cedar post of some vintage lying on the ground about 10 ft. S, but nothing to show where it had been placed in the ground.

**Corner 16:** Established on line between Sec. Cor. 20.023 ch. E and 1/4 cor. 20.023 ch. W.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

**Corner I-5:** 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.  
 Cedar 7 S70°W (mag.) 14.6 ft. "S15, NBT"  
 Cedar 7 S42°E (mag.) 2.4 ft. "S14, NBT"  
 Cedar 9 N29°W (mag.) 6.2 ft. "S10, NBT"  
 Also squared and scribed a 5" cedar S51°E 0.6 ft. (to center).  
 Declination is 0°45' East.

**Corner 16:** 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.  
 Red Maple 4 S50°W (mag.) 14.1 ft. "1/16S, BT"  
 Red Maple 6 S51°E (mag.) 13.0 ft. "1/16S, BT"  
 Declination is 0°10' West. Distances are horizontal.

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY Arthur O. Enger CHIEF OF SURVEY PARTY DATE August 22, 1977  
 MICHIGAN REGISTERED LAND SURVEYOR

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

