

SURVEY & REMONUMENTATION

FEB 18 1994

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in **BRADY TWP.**

<u>KALAMAZOO</u> <small>(County)</small>	Located In:	Corner Code #
1. Public Land Survey	T <u>4S</u> R <u>10W</u>	<u>C-1</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

STATE OF MICHIGAN
 COUNTY OF KALAMAZOO
 RECEIVED FOR RECORD
 94 JAN 20 PM 3 09
 J. H. ...
 CLERK - REGISTER

Register of Deeds Stamp & File Number

LIBER **1** PG **1072**

I, Allen H. McMachen a field surveyor on December 4, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

1987 - Iron Rod found 1.5' deep. Found Iron was East 52.8' (rec. G.L.O. = 52.8') from found Clay Tile at S.E. corner of Section 31, Pavilion Twp., I.W.M. placed an Iron Rod over the deeper found Iron, accessories:

- 8" Hick N. 75 deg. E. 29.32'
- 8" Hick N. 30 deg. E. 25.37'
- Utility pole West 23.83'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 24" long Iron Rod at surface, 6" above a 18" long Iron Rod. Dug 3' x 3' x 5' deep. Finding no further evidence of corner.

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
12-16-93



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found Iron Rod is accepted as a careful and faithful perpetuation of the original corner. Removed both found Irons and placed Harrison Monument, accessories:

- | | | | |
|-------------------------|------|-------------|----------------------|
| Nail & Tab in East | face | 10" Hickory | N. 24 deg. E. 16.42' |
| Nail & Tab in Southeast | face | 10" Hickory | N. 64 deg. E. 29.29' |
| Nail & Tab in East | face | 10" Hickory | N. 24 deg. W. 25.23' |
| Nail & Tab in South | face | Util. Pole | S. 86 deg. W. 23.92' |

Signed by Allen H. McMachen Date 1/20/94
 Surveyor's Michigan License No. 16935