

MAR 20 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
Mackinac County Remonumentation Corner

For corners in

Mackinac Located In: Corner Code #
1. Public Land Survey T 43N R 10W
T 43N R 11W
2. Property Controlling S T R
In Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

(A-9) M-9

RECEIVED & FILED
DIANE FRANKOVICH
MACKINAC COUNTY REGISTER OF DEEDS

DEC 30 1999

AM PM
7|8|9|10|11|12|1|2|3|4|5|6

Register of Deeds Stamp & File Number

4. Lot No. Recorded Plat
5. Private Claims

I, William L. Karr, in a field survey on July 13, 1999, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Grid table with columns A-M and rows 1-13. Handwritten annotations 'T43N' and 'R10W' are present across the grid.

A. Description of original monument and accessories and/or subsequent restoration:
(A-9) Section corner common to Sections 19 & 30, Township 43 North, Range 10 West, and Sections 24 & 25, Township 43 North, Range 11 West.

- 1849 William Ives, D.S. set post Fir 10 S84°W 20
Fir 12 N34°E 25
1986 Neil Hill, P.S. 27447 found no evidence of the original corner or subsequent restoration and used a DNR survey in Section 24, Township 43 North, Range 11 West to reset corner. Set 1/2" iron in monument box and recorded in Liber C, Page 173 of the Mackinac County Corner Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
(A-9) Section corner common to Sections 19 & 30, Township 43 North, Range 10 West, and Sections 24 & 25, Township 43 North, Range 11 West.
Found 1/2" iron with P.S. cap no. 27447 in monument box and one remaining witness. Accepted corner position as found. Corner was to be destroyed during road reconstruction of U.S. 2. and was rewitnessed prior to construction.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
(A-9) Section corner common to Sections 19 & 30, Township 43 North, Range 10 West, and Sections 24 & 25, Township 43 North, Range 11 West.
After road reconstruction set 1/2" iron with 3" stamped aluminum Mackinac County Remonumentation corner cap in monument box. Road stationing MDOT plans dated 7/21/97 is 27+216.79.

Witnesses:

- 1/2" Re-rod North 90.93 feet
Power Pole S11°E 151.35 feet
Drill Hole Top
Center of Concrete
ROW Marker S20°W 67.44 feet (existing)
Poplar 12" N41°W 136.84 feet

ACCEPTED BY THE MACKINAC COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER P.A. 345 OF 1990 AT A MEETING HELD ON 11-05-99 NEH



Signed by [Signature] Date 12/16/99

Surveyor's Michigan License No. 27450

NOTE: All bearings are compass bearings corrected for declination (6°W). All distances are to a nail and tag in the side of witness object unless otherwise noted.